



Avaya Solution & Interoperability Test Lab

Application Notes for Configuring Cofely Quentris® Smile R2.5 with Avaya Communication Server 1000E R7.5 – Issue 1.0

Abstract

These Application Notes describe the configuration steps necessary for Cofely Quentris® Smile 2.5 to successfully interoperate with Avaya Communication Server 1000E R7.5.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

1. Introduction

These Application Notes describe a compliance-tested configuration of the interoperability of Cofely Quentris® Smile 2.5 to successfully interoperate with Avaya Communication Server 1000E R7.5 (CS1000E). Cofely Quentris® Smile 2.5 is a screen based console or “soft-console,” that is installed on a Personal Computer (PC). It interfaces directly using a serial connection to either the M2250 console or a Console Interface Unit (CIU) on the CS1000E and provides a graphical user interface for call handling. All relevant call information is provided on a single window. Cofely Quentris® Smile 2.5 provides call handling capabilities, enabling operators to answer, transfer, announce, park, hold and place calls using their PC. The Cofely Quentris® Smile 2.5 main screen holds all information related to a call such as name, number, origin and status.

2. General Test Approach and Test Results

The Cofely Quentris® Smile 2.5 (Smile 2.5) is not configured on the CS1000E; it is simply connected via a serial cable to an existing M2250 or CIU running on the CS1000E. The Smile 2.5 console provides management of multiple lines. The Smile 2.5 console is programmed with up to 6 hold keys for queuing incoming calls. Smile 2.5 uses the Avaya implementation of Calling Line ID (CLID) and Dialed Number Identification Service (DNIS) to perform directory lookups. Testing was carried out in the Avaya Lab. Test cases were executed jointly by an Avaya and Cofely Quentris representative.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member’s solution.

2.1. Interoperability Compliance Testing

During interoperability compliance testing the following features of Smile 2.5 was tested:

- Call handling capabilities including Call Answering, Call Transfer, Announce, Call Park, Call Hold / Unhold.
- Placing of calls both internally or externally by the Operator.
- BLF (Busy Lamp Field) provision of the status of the various internal handset types.
- Calling Line Identification (CLID) and Dialed Number Identification Service (DNIS) support for PSTN trunks.
- Support for Call Party Name Display.
- Call Waiting indicator (DWC).
- ATDN, LDN, Private DN, ACD.
- Night number.
- Local internal call handling.
- Handling of calls to and from Avaya IP UNISim, SIP and Digital phone sets

2.2. Test Results

All tests outlined in the Test Plan document passed successfully. The following observation was noted.

- When the CIU is “reset” using the reset button at the back, the light at the front remains lit in an orange colour and the only way to get it working again is to disable the XDLC and re-enable it.

2.3. Support

For more information on Cofely Quentris® Smile 2.5 and product support, visit <http://www.smileconsole.com/>. The following is the contact information for Cofely Quentris:

COFELY QUENTRIS (GDF SUEZ)
Rue de la Fusée 60 Raketstraat - B-1130 Brussels
+32 2 727 15 81
www.cofelyquentris-gdfsuez.be

3. Reference Configuration

The configuration in **Figure 1** was used to compliance test Smile 2.5 with the CS1000E using a serial cable connecting from the Smile 2.5 PC to the M2250 Console or the CIU depending on the hardware being used. Note that the connection type is the same for both consoles and both consoles are programmed in the exact same way as per **Section 5**.




Figure 1: Reference Configuration of Cofely Quentris® Smile 2.5 and Avaya Communication Server 1000E R7.5.

4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided:

Equipment Description	Software Release
Avaya Communication Server 1000E running on Avaya CPPM	R7.5 (See Appendix for a list of Patches)
Avaya Aura [®] Session Manager running on an Avaya S8800 Server	R6.2 SP4
Avaya Aura [®] System Manager running on an Avaya S8800 Server	R6.2 SP4
Avaya M2250 Console	N/A
Avaya Console Interface Unit (CIU)	N/A
Avaya 1140 UNISlim Deskphone	UNISlim V0625C8D
Avaya 1140 SIP Deskphone	SIP V04.00.04.00
Desktop PC (Minimum Specification Pentium IV, 3 GHz, 1 GB Ram, 1 USB Hand/Headset) <ul style="list-style-type: none">Smile 2.5 Installation Disk and License	Microsoft Windows XP <ul style="list-style-type: none">Version 2.5.1

5. Configuration of Avaya Communication Server 1000E

It is assumed that a fully functioning CS1000E is in place with the necessary licensing. For further information on the configuration of CS1000E please see **Section 9** of these Application Notes. A telnet client such as “Putty” is used to administer the CS1000E. Open an SSH session to the Node IP address of the CS1000E, login to the CS1000E Linux application using the appropriate credentials and type **cslogin** (not shown) to gain access to the PBX command line.

Note: A simulated PSTN connection was added to the configuration. This is out of scope to be documented in these Application Notes.

Note: Not all prompts need an answer. The prompts outlined below are mandatory for a basic configuration. Accept the default responses for all other prompts by pressing the return key.

5.1. Configuration of the M2250 Console

The following setup of the attendant was used for compliance testing. Please note that some of the information described in the following sections will be required during the Smile 2.5 setup in **Section 6**. Type **LD 12** at the > prompt to enter overlay 12 and create a **NEW 2250** console as shown below.

Note: All other values can be left as default by pressing return when prompted for a value.

Prompt	Response	Description
>	LD 12	Enter Overlay 12
REQ	NEW	New Attendant
TYPE	2250	TYPE 2250 Attendant Console
CUST	0	Customer number
TN	4 0 2 3	Loop Shelf Card Unit of the M2250 Console
SETN	4 0 2 4	Secondary TN of the M2250
ANUM	1	Console Number
ICDR	ICDD	Internal Call Detail Recording (Denied)
ABAN	ABDD	Abandoned call record and time to answer (Denied)
CPND	CNDA	Call Party Name Display feature Allowed
DNDI	DNDA	Dialed Name Display Allowed
DAPC	DAPA	Dial Access Prefix on Console Allowed
KEY 00	BVR	Allow Busy Verify on key 0.
KEY 01	BIN	Allow Barge-In on key 01.
KEY 02	SSC 0010	System Speed call on key 02
KEY 03	DPS	Display Source key on key 03
KEY 04	DPD	Display Destination key on key 04
KEY 05	PRK	Call Park Key on key 05
KEY 06	ADL	Autodial key on key 06
KEY 07	MTM	Maintain Change/Display Time key on key 07
KEY 08	MDT	Maintain Change/Display Date key on key 08
KEY 09	BKI	Break-in Key on key 09
KEY 10		
KEY 11	MIK	Message Indication key on key 11
KEY 12	MCK	Message Cancellation key on key 12
KEY 13	AWU	Automatic Wake Up on key 13
KEY 14	RDL	Redial stored number on key 14
KEY 15	EES	End to end signaling on key 15
KEY 16	PRK	Call Park on key 16

5.2. Configuration of Customer Data Block

Enter overlay 15 to make changes to the Customer Data Block (CDB) specifically the Attendant Data (ATT) and the Night Number (NIT).

5.2.1. Attendant Data (ATT) Configuration

Type **LD 15** at the **>** prompt to enter overlay 15. Type **CHG** at the **REQ** prompt and **ATT** at the **TYPE** prompt to make changes to the Attendant data. The following should be set to ensure that the SMILE software works properly with the Attendant Console configured in **Section 5.1** above.

Note: All other values can be left as default by pressing return when prompted for a value.

Prompt	Response	Description
>	LD 15	Enter Overlay 15
REQ	CHG	Change
TYPE	ATT	Attendant Data
OPT	ABDD	Attendant Busy Display Denied
	AHA	Auto Hold Allowed
	EBIN	Extended Break-In Indication
	BIXA	Break-In to external call Allowed
	BLA	Break-In to Line Lockout Set Allowed
	BOHD	Position Busy with Calls on Hold Denied
	CHDA	Charge Display Allowed at end of call
	DRE	Queue thermometer REST Excludes Inter-Attendant calls, Recalls and Metered calls
	DNX	ACD Dialed Number Identification Service feature excluded
	FACD	Flexible Attendant Call Waiting (ACW) thresholds Allowed Call Waiting thresholds are expressed as a percentage of the active consoles
	IC1	Incoming Call Indicator key/lamp strips
	ITG	Include key/lamp expansion module
	IDP	Include Digit Display
	XLF	Exclude Lamp Field array
	XBL	Exclude Enhanced Busy Lamp Field
	FKA	Forward Key Allowed
	MCTD	Malicious Call Trace signal Denied
	NCD	When an Attendant Console Group (ACG) is in Night Service, redirection of attendant calls is denied.
	CUI	CI lamps show Attendant Console Group (ACG) information for incoming calls
	MWUD	Message Waiting Unconditional Denied
	LOA	Lockout Allowed
	PSA	Presentation Status selection Allowed on attendant consoles
	RECA	Attendant calls are redirected when all but one console is busy
	REA	Release on Exclusion Allowed
	EHS	Enhanced Secrecy Allowed
	SLD	Slow Answer Recall Enhancement Denied
	SIAD	Source Included when Attendant dials Denied
	THPD	ACD Threshold Percentage Denied
	ATDA	Attendant through Dialling Allowed
ATDN	0	Number to call the Attendant
CWUP	YES	Call Waiting queue Update
CWCL	0 2	Call Waiting Call Limit
CWTM	0 10	Lower and upper thresholds for Call Waiting Time
CWBZ	YES YES	Call Waiting Buzz

RTIM	30 30 30	Recall (for Slow-Answer) (for Camp-On) (for Call waiting)
ATIM	30	Attendant Alternative Answering Timer
AQTT	30	Attendant Queue Timing Threshold in seconds
RTSA	RSAX	Recall to Same Attendant allowed, with queuing on busy attendant
...		
ICI 00	LD0 RDI	ICI number, RDI intercept
ICI 01	CFN CFB	ICI number, Call Forward No Answer, Call Forward Busy
ICI 02	RLL	ICI number, Recall
ICI 03	DL0	ICI number, dial 0
ICI 04	INT	ICI number, Intercept
ICI 05	MTR	ICI number, Meter Recall
ICI 06	MWC	ICI number, Message Waiting Calls
...		
RICI	0 1 3 4	ICI key numbers that may receive Recorded Overflow Announcement

5.2.2. NIT Data Configuration

Stay in **LD 15**, type **CHG** at the **REQ** prompt and **NIT** at the **TYPE** prompt to make changes to the NITE data. In the example below the prompt **NIT** is changed to a DN on a specific phone set. When the M2250/CIU is placed into “NITE”, callers dialling the console number (LDNs, ATDN, etc...) are routed to the NIT number defined in the customer data block which will be as per the example below the DN 3500.

Prompt	Response	Description
>	LD 15	Enter Overlay 15
REQ	CHG	Change existing customer data block
TYPE	NIT_DATA	Night Service options
CUST	0	Customer number
NIT1	3500	Extension number 3500

5.3. Busy Lamp Field Configuration

The BLF can be configured to display the status of:

- A specified 150 consecutive DNs (Standard Busy Lamp Field - SBLF)
- All DNs, 100 at a time (Enhanced Busy Lamp Field - EBLF)

5.3.1. Standard Busy Lamp Field

Stay in overlay 15 or type **LD 15** at the > prompt to enter overlay 15. Type **CHG** at the **REQ** prompt and **ATT** at the **TYPE** prompt to make changes to the Attendant data. Ensure that **OPT** is set to **ILF** for a Standard Busy Lamp Field.

Prompt	Response	Description
>	LD 15	Enter Overlay 15
REQ	CHG	Change
TYPE	ATT	Attendant Data
OPT	ILF	

The following change must be made in overlay 12 to the M2250 console for standard BLF. Type **LD 12** at the > prompt to enter overlay 12. Type **CHG** at the **REQ** prompt and **2250** at the **TYPE** prompt to make changes to the Attendant console. Ensure that EBLF is set to BLFD.

>	LD 12	Enter Overlay 12
REQ	CHG	Change Attendant
TYPE	2250	TYPE 2250 Attendant Console
CUST	0	Customer number
TN	4 0 2 3	Loop Shelf Card Unit of the M2250 Console
....		
EBLF	BLFD	Enhanced Busy Lamp Field Denied

5.3.2. Enhanced Busy Lamp Field

The following change is made to the Attendant Data in overlay 15 for the enhanced BLF. Ensure that **OPT** is set to **ILB** for an Enhanced Busy Lamp Field.

Prompt	Response	Description
>	LD 15	Enter Overlay 15
REQ	CHG	Change
TYPE	ATT	Attendant Data
OPT	ILB	

The following change must be made in overlay 12 to the M2250 console for enhanced BLF. Type **LD 12** at the > prompt to enter overlay 12. Type **CHG** at the **REQ** prompt and **2250** at the **TYPE** prompt to make changes to the Attendant console. Ensure that EBLF is set to BLFA.


>	LD 12	Enter Overlay 12
REQ	CHG	Change Attendant
TYPE	2250	TYPE 2250 Attendant Console
CUST	0	Customer number
TN	4 0 2 3	Loop Shelf Card Unit of the M2250 Console
....		
EBLF	BLFA	Enhanced Busy Lamp Field Allowed

6. Configure Cofely Quentris® Smile 2.5 Console Application


It is expected that the Smile 2.5 installation and license activation is completed before the following configuration can be executed. For details on how these procedures are carried out please refer to **Section 9** of these Application Notes.

6.1. Configure Cofely Quentris® Smile 2.5 using Configuration Wizard

Navigate to **C:\Program Files\Smile** (or wherever the Smile was installed) and open the configuration wizard by double-clicking on **config.exe** as highlighted below.



Accept the default installation path (unless otherwise required) and click **Next** to continue through the wizard.



Please note that under **Settings**, the choice is made between **M2250** and **CIU** depending on the Avaya Hardware Console that is being connected to. Please choose either M2250 or CIU. For all other settings consult with the *The Cofely Quentris Smile 2 Technical Guide, Version 1.6* (page 51), as these settings will depend on the unique setup of the individual user. Click **Next** to continue through the wizard.

Smile Configuration

Please select the options pertaining to your Smile 2 installation

Calls Waiting Maximum

5 10 20
 50 100

Critical call waiting:

Settings

Protocol: Port:

Console ID:

Password:

Outgoing Calls

Search mechanism

	Prefix	Charge Acc.
External Number :	<input type="text" value="9"/>	<input type="text" value="Don't use"/>
Mobile Number :	<input type="text" value="9"/>	<input type="text" value="Don't use"/>
Forward 1 :	<input type="text"/>	<input type="text" value="Don't use"/>
Forward 2 :	<input type="text"/>	<input type="text" value="Don't use"/>
Network Number :	<input type="text"/>	<input type="text" value="Don't use"/>

Fixed Account Code length:

Busy Lamp Field

PanelType:

Base Extension:

Incoming Calls

Algorithm: Smile FIFO

SeekMode:

Unknown incoming call notification

Calls OnHold

Threshold: Sec.

Mail Express

Mail Express Number:

Mail Express Timer: Sec.


Inter Digit Timer: mSec.

Connection string:

Info: [Em_Number] = the 'mail express number' will automatically be inserted
 [Em_Timer] = a pause of x sec will be applied (Mail Express Timer)
 [EES] = activate / deactivate E.E.S
 [Mailbox] = the selected mailbox number will be inserted here
 . = a pause of 2 sec will be applied

Exit **Next >**

Fill in the ICI and feature key numbers according to the setup in **Section 5.1** and **Section 5.2.1** above. Click **Next** to continue.




The image shows a software window titled "Smile Configuration". The window has a blue title bar with a close button in the top right corner. Below the title bar, there is a yellow smiley face icon and a text prompt: "Please enter the positions of the Common ICI Keys and Feature Keys".

The configuration area is divided into two sections:


- Common ICI Keys:** This section contains six input fields arranged in two columns. The left column has "Recall" (2), "Intercept" (4), and "Operator" (3). The right column has "Ldn" (0), "VIP" (5), and "CFNA" (1).
- Common Feature Keys:** This section contains five input fields arranged in two columns. The left column has "Display" (4), "EES" (5), and "CHG" (0). The right column has "Date" (8) and "Time" (7).

At the bottom right of the window, there are two buttons: "Exit" and "Next >". The "Next >" button is highlighted with a red rectangular border.


The default settings were accepted, click on **Next** to continue.




LDAP was not tested so the tick-box was left unchecked. If LDAP is required then this tick-box should be selected and the LDAP Server information entered on this screen. Click on **Next** to continue.




Networking was not tested so the tick-box was left unchecked. If **networking** is required then this tick-box should be selected. Click on **Next** to continue.



Smile Mail Service was not tested so the tick-box was left unchecked. If Smile Mail Service is required then this tick-box should be selected. Click on **Next** to continue.




Once the necessary information has been filled in correctly click on **End** as highlighted below.




7. Verification Steps


To ensure that Smile 2.5 with CS1000E have been integrated successfully launch the Smile 2.5 console as shown below.



Once logged in the Smile 2.5 screen displays the following. Note the Extension numbers in the Busy Lamp Field and the console is in an **Idle** state, ready to take a call.



The following screen shows a call that is being made from extension **3202** to the **Operator**. Note the busy lamp field shows busy for ext 3202 and the display gives the extension number and the Name. Note also that the “Telephone Icon” has changed from a yellow colour, as seen in the screen shot above to a red colour, seen below. The console state has now gone to **Active**.



8. Conclusion

The interoperation of Cofely Quentris® Smile 2.5 with Avaya Communication Server 1000E was successful and did not impact on the operation of the Avaya Communication Server 1000E. No major issues were found for all compliance tests as per **Section 2.2**.

9. Additional References

Additional Avaya product documentation is available at <http://support.avaya.com>.

- [1] *Software Input Output Reference – Administration – Avaya Communication Sever 1000, R7.5 NN43001-611, 05.09 Sept 2011*

Information on the installation and configuration of Cofely Quentris ® Smile 2.5 can be found at <http://www.smileconsole.com>.

- [1] *The Cofely Quentris Smile 2 Technical Guide, Version 1.6*

Appendix A

List of Linux Patches on Avaya Communication Server 1000E R7.5

```
[paul@cs1kpg ~]$ pstat
Product Release: 7.50.17.00
In system patches: 1
PATCH# NAME IN_SERVICE DATE SPECINS TYPE RPM
31 p31484_1 Yes 17/01/13 NO FRU cs1000-shared-general-7.50.17-00.i386

In System service updates: 31
PATCH# IN_SERVICE DATE SPECINS REMOVABLE NAME
0 Yes 16/01/13 NO YES cs1000-linuxbase-7.50.17.16-13.i386.000
1 Yes 16/01/13 YES YES cs1000-baseWeb-7.50.17.16-2.i386.000
2 Yes 16/01/13 NO YES cs1000-patchWeb-7.50.17.16-8.i386.000
3 Yes 17/01/13 NO YES cs1000-shared-pbx-7.50.17.16-1.i386.000
4 Yes 17/01/13 NO YES cs1000-kcv-7.50.17.16-1.i386.000
5 Yes 17/01/13 NO yes avaya-cs1000-cnd-4.0.20-00.i386.000
6 Yes 17/01/13 NO YES cs1000-ipsec-7.50.17.16-1.i386.000
7 Yes 17/01/13 NO YES ipsec-tools-0.6.5-14.el5.3_avaya_1.i386.000
8 Yes 17/01/13 NO YES spiritAgent-6.1-1.0.0.108.208.i386.000
9 Yes 17/01/13 NO YES cs1000-mscTone-7.50.17.16-1.i386.000
10 Yes 17/01/13 NO yes tzdata-2011h-2.el5.i386.000
11 Yes 17/01/13 NO YES cs1000-pd-7.50.17.16-1.i386.000
12 Yes 17/01/13 NO YES cs1000-ncs-7.50.17.16-1.i386.000
13 Yes 17/01/13 NO YES cs1000-EmCentralLogic-7.50.17.16-2.i386.000
14 Yes 17/01/13 NO YES cs1000-cs1000WebService_6-0-7.50.17.16-1.i386.000
15 Yes 17/01/13 NO YES cs1000-mscMusc-7.50.17.16-11.i386.000
16 Yes 17/01/13 NO YES cs1000-mscAnnc-7.50.17.16-10.i386.000
17 Yes 17/01/13 NO YES cs1000-csoneksvrmgr-7.50.17.16-1.i386.000
18 Yes 17/01/13 NO YES cs1000-bcc-7.50.17.16-69.i386.000
19 Yes 17/01/13 NO YES cs1000-csmWeb-7.50.17.16-6.i386.000
20 Yes 17/01/13 NO YES cs1000-mscConf-7.50.17.16-1.i386.000
21 Yes 17/01/13 NO YES cs1000-emWeb_6-0-7.50.17.16-34.i386.000
22 Yes 17/01/13 NO YES cs1000-Jboss-Quantum-7.50.17.16-30.i386.000
23 Yes 17/01/13 NO YES cs1000-tps-7.50.17.16-24.i386.000
24 Yes 17/01/13 NO YES cs1000-sps-7.50.17.16-10.i386.000
25 Yes 17/01/13 NO YES cs1000-ftpkg-7.50.17.16-11.i386.000
26 Yes 17/01/13 NO YES cs1000-emWebLocal_6-0-7.50.17.16-3.i386.000
27 Yes 17/01/13 NO YES cs1000-dmWeb-7.50.17.16-6.i386.000
28 Yes 17/01/13 NO YES cs1000-dbcom-7.50.17.16-1.i386.000
29 Yes 17/01/13 NO YES cs1000-vtrk-7.50.17.16-131.i386.001
30 Yes 17/01/13 NO YES cs1000-mscAttn-7.50.17.16-3.i386.000
[paul@cs1kpg ~]$
```

List of Call Server Patches on Avaya Communication Server 1000E R7.5

```
.mdp issp

VERSION 4121
RELEASE 7
ISSUE 50 Q +
DepList 1: core Issue: 01 (created: 2013-01-11 11:29:20 (est)) ALTERED

IN-SERVICE PEPS
PAT# CR #          PATCH REF #      NAME          DATE          FILENAME          SPECINS
000 wi00965603      ISS1:1OF1        p31618_1      17/01/2013    p31618_1.cpl     NO
001 wi01044868      ISS1:1OF1        p32261_1      17/01/2013    p32261_1.cpl     NO
002 wi01031887      ISS1:1OF1        p31814_1      17/01/2013    p31814_1.cpl     NO
003 wi01001588      ISS1:1OF1        p31976_1      17/01/2013    p31976_1.cpl     NO
004 wi00977002      ISS2:1OF1        p30786_2      17/01/2013    p30786_2.cpl     NO
005 wi01043458      ISS1:1OF1        p31712_1      17/01/2013    p31712_1.cpl     NO
006 wi01016398      ISS1:1OF1        p32019_1      17/01/2013    p32019_1.cpl     NO
007 wi01042797      ISS1:1OF1        p32089_1      17/01/2013    p32089_1.cpl     NO
008 wi01022466      ISS1:1OF1        p32205_1      17/01/2013    p32205_1.cpl     NO
009 wi00965009      ISS1:1OF1        p31600_1      17/01/2013    p31600_1.cpl     NO
010 wi01033197      ISS1:1OF1        p29818_1      17/01/2013    p29818_1.cpl     NO
011 wi01034409      ISS1:1OF1        p29708_1      17/01/2013    p29708_1.cpl     NO
012 wi01028650      ISS1:1OF1        p32188_1      17/01/2013    p32188_1.cpl     NO
013 wi01039079      ISS1:1OF1        p32210_1      17/01/2013    p32210_1.cpl     NO
014 wi00967505      ISS1:1OF1        p31491_1      17/01/2013    p31491_1.cpl     NO
015 wi00971980      ISS1:1OF1        p31863_1      17/01/2013    p31863_1.cpl     NO
016 wi01041545      ISS1:1OF1        p32236_1      17/01/2013    p32236_1.cpl     YES
017 wi01039099      ISS1:1OF1        p32269_1      17/01/2013    p32269_1.cpl     NO
018 wi00854469      ISS1:1OF1        p30701_1      17/01/2013    p30701_1.cpl     NO
019 wi01031571      ISS1:1OF1        p32158_1      17/01/2013    p32158_1.cpl     NO
020 wi01021598      ISS1:1OF1        p32066_1      17/01/2013    p32066_1.cpl     NO
021 wi01029486      ISS1:1OF1        p32144_1      17/01/2013    p32144_1.cpl     NO
022 wi01044828      ISS1:1OF1        p31510_1      17/01/2013    p31510_1.cpl     NO
023 wi01034452      ISS1:1OF1        p31672_1      17/01/2013    p31672_1.cpl     NO
024 wi01023570      ISS1:1OF1        p32096_1      17/01/2013    p32096_1.cpl     NO
025 wi01005653      ISS1:1OF1        p31952_1      17/01/2013    p31952_1.cpl     NO
026 wi01033893      ISS1:1OF1        p32167_1      17/01/2013    p32167_1.cpl     NO
027 wi01001911      ISS1:1OF1        p31920_1      17/01/2013    p31920_1.cpl     NO
028 wi01045924      ISS1:1OF1        p32259_1      17/01/2013    p32259_1.cpl     NO
029 wi01032447      ISS1:1OF1        p32160_1      17/01/2013    p32160_1.cpl     NO
030 wi01008943      ISS1:1OF1        p31382_1      17/01/2013    p31382_1.cpl     NO
031 wi01030088      ISS1:1OF1        p32148_1      17/01/2013    p32148_1.cpl     YES
032 wi01020230      ISS2:1OF1        p32057_2      17/01/2013    p32057_2.cpl     YES
033 wi01031640      ISS1:1OF1        p31607_1      17/01/2013    p31607_1.cpl     YES
034 wi01044026      ISS1:1OF1        p32249_1      17/01/2013    p32249_1.cpl     NO
035 wi01011113      ISS1:1OF1        p32054_1      17/01/2013    p32054_1.cpl     NO
036 wi01007604      ISS1:1OF1        p31983_1      17/01/2013    p31983_1.cpl     NO
037 wi01020587      ISS1:1OF1        p32097_1      17/01/2013    p32097_1.cpl     NO
038 wi00993743      ISS1:1OF1        p31865_1      17/01/2013    p31865_1.cpl     NO
039 wi01014835      ISS1:1OF1        p32015_1      17/01/2013    p32015_1.cpl     NO
040 wi01027609      ISS1:1OF1        p31850_1      17/01/2013    p31850_1.cpl     NO
041 wi01042755      ISS1:1OF1        p31667_1      17/01/2013    p31667_1.cpl     NO
042 wi01033550      ISS1:1OF1        p31565_1      17/01/2013    p31565_1.cpl     NO
043 wi01018064      ISS1:1OF1        p32044_1      17/01/2013    p32044_1.cpl     NO
044 wi01042548      ISS1:1OF1        p32232_1      17/01/2013    p32232_1.cpl     NO
045 wi01037234      ISS1:1OF1        p32220_1      17/01/2013    p32220_1.cpl     NO
046 wi01027702      ISS1:1OF1        p32140_1      17/01/2013    p32140_1.cpl     NO
047 wi01016303      ISS1:1OF1        p32031_1      17/01/2013    p32031_1.cpl     NO
048 wi01042791      ISS1:1OF1        p32234_1      17/01/2013    p32234_1.cpl     NO
```

049	wi00897279	ISS1:1OF1	p31129_1	17/01/2013	p31129_1.cpl	NO
050	wi01034420	ISS1:1OF1	p31584_1	17/01/2013	p31584_1.cpl	NO
051	wi01044293	ISS1:1OF1	p32250_1	17/01/2013	p32250_1.cpl	NO
052	wi01020752	ISS1:1OF1	p32108_1	17/01/2013	p32108_1.cpl	NO
053	wi01006063	ISS1:1OF1	p31957_1	17/01/2013	p31957_1.cpl	NO
054	wi01008505	ISS1:1OF1	p31968_1	17/01/2013	p31968_1.cpl	NO
055	wi01008106	ISS1:1OF1	p31861_1	17/01/2013	p31861_1.cpl	NO
056	wi00976951	ISS1:1OF1	p30112_1	17/01/2013	p30112_1.cpl	NO
057	wi01050993	ISS1:1OF1	p32289_1	17/01/2013	p32289_1.cpl	NO
058	wi00837538	ISS1:1OF1	p30568_1	17/01/2013	p30568_1.cpl	NO
059	wi01020959	ISS1:1OF1	p32062_1	17/01/2013	p32062_1.cpl	NO
060	wi01013144	ISS1:1OF1	p31929_1	17/01/2013	p31929_1.cpl	NO
061	wi00978818	ISS1:1OF1	p31919_1	17/01/2013	p31919_1.cpl	NO
062	wi00999802	ISS1:1OF1	p31577_1	17/01/2013	p31577_1.cpl	NO
063	wi01039170	ISS1:1OF1	p32207_1	17/01/2013	p32207_1.cpl	YES
064	wi00978892	ISS1:1OF1	p31894_1	17/01/2013	p31894_1.cpl	NO
065	wi01014478	ISS1:1OF1	p32301_1	17/01/2013	p32301_1.cpl	NO
066	wi01012423	ISS1:1OF1	p26155_1	17/01/2013	p26155_1.cpl	NO
067	wi01012229	ISS1:1OF1	p31993_1	17/01/2013	p31993_1.cpl	NO
068	wi01042118	ISS1:1OF1	p32231_1	17/01/2013	p32231_1.cpl	NO
069	wi01030651	ISS1:1OF1	p32159_1	17/01/2013	p32159_1.cpl	NO
070	wi01031825	ISS1:1OF1	p31882_1	17/01/2013	p31882_1.cpl	NO
071	wi01051024	ISS1:1OF1	p32290_1	17/01/2013	p32290_1.cpl	NO
072	wi01032794	ISS1:1OF1	p31480_1	17/01/2013	p31480_1.cpl	NO
073	wi01003896	ISS1:1OF1	p31631_1	17/01/2013	p31631_1.cpl	NO
074	wi01031512	ISS1:1OF1	p32154_1	17/01/2013	p32154_1.cpl	YES
075	wi01037848	ISS1:1OF1	p32202_1	17/01/2013	p32202_1.cpl	NO
076	wi00896319	ISS1:1OF1	p31070_1	17/01/2013	p31070_1.cpl	NO
077	wi01039486	ISS1:1OF1	p32209_1	17/01/2013	p32209_1.cpl	YES
078	wi01008188	ISS1:1OF1	p32020_1	17/01/2013	p32020_1.cpl	NO
079	wi01037022	ISS1:1OF1	p32192_1	17/01/2013	p32192_1.cpl	YES
080	wi01000796	ISS1:1OF1	p31800_1	17/01/2013	p31800_1.cpl	NO
081	wi01050057	ISS1:1OF1	p32286_1	17/01/2013	p32286_1.cpl	NO
082	wi01051786	ISS1:1OF1	p32296_1	17/01/2013	p32296_1.cpl	YES
083	wi01040096	ISS1:1OF1	p32214_1	17/01/2013	p32214_1.cpl	NO
084	wi01037975	ISS1:1OF1	p32227_1	17/01/2013	p32227_1.cpl	YES
085	wi00998328	ISS1:1OF1	p31899_1	17/01/2013	p31899_1.cpl	NO
086	wi01011078	ISS1:1OF1	p31996_1	17/01/2013	p31996_1.cpl	NO
087	wi01044600	ISS1:1OF1	p32255_1	17/01/2013	p32255_1.cpl	YES
088	wi01036339	ISS1:1OF1	p32204_1	17/01/2013	p32204_1.cpl	NO
089	wi00967507	ISS1:1OF1	p31416_1	17/01/2013	p31416_1.cpl	NO
090	wi01041007	ISS1:1OF1	p32059_1	17/01/2013	p32059_1.cpl	NO
091	wi01001938	ISS1:1OF1	p31921_1	17/01/2013	p31921_1.cpl	YES
092	wi01043882	ISS1:1OF1	p32248_1	17/01/2013	p32248_1.cpl	YES
093	wi01044873	ISS1:1OF1	p31749_1	17/01/2013	p31749_1.cpl	NO
094	wi01057299	ISS1:1OF1	p32367_1	17/01/2013	p32367_1.cpl	NO
095	wi01046101	ISS1:1OF1	p32263_1	17/01/2013	p32263_1.cpl	NO
096	wi01034774	ISS1:1OF1	p32173_1	17/01/2013	p32173_1.cpl	NO
097	wi01005927	ISS1:1OF1	p31905_1	17/01/2013	p31905_1.cpl	NO
098	wi01015780	ISS1:1OF1	p32083_1	17/01/2013	p32083_1.cpl	NO
099	wi01003861	ISS1:1OF1	p32113_1	17/01/2013	p32113_1.cpl	YES
100	wi00996889	ISS1:1OF1	p31933_1	17/01/2013	p31933_1.cpl	NO
101	wi01007960	ISS1:1OF1	p31965_1	17/01/2013	p31965_1.cpl	NO
102	wi01012638	ISS1:1OF1	p32008_1	17/01/2013	p32008_1.cpl	NO
103	wi01034779	ISS1:1OF1	p32174_1	17/01/2013	p32174_1.cpl	NO
104	wi00991907	iss1:1of1	p31907_1	17/01/2013	p31907_1.cpl	NO
105	wi01028950	ISS1:1OF1	p31782_1	17/01/2013	p31782_1.cpl	NO
106	wi01008316	ISS1:1OF1	p32026_1	17/01/2013	p32026_1.cpl	YES
107	wi01037773	ISS1:1OF1	p31544_1	17/01/2013	p31544_1.cpl	NO
108	wi00949136	ISS1:1OF1	p31441_1	17/01/2013	p31441_1.cpl	NO
109	wi01044845	ISS1:1OF1	p31739_1	17/01/2013	p31739_1.cpl	NO
110	wi01046277	ISS1:1OF1	p32265_1	17/01/2013	p32265_1.cpl	NO

111	wi01037583	ISS1:1OF1	p32201_1	17/01/2013	p32201_1.cpl	NO
112	wi01010472	ISS1:1OF1	p31975_1	17/01/2013	p31975_1.cpl	NO
113	WI01018404	ISS1:1OF1	p31568_1	17/01/2013	p31568_1.cpl	NO
114	wi01043713	ISS1:1OF1	p32245_1	17/01/2013	p32245_1.cpl	YES
115	wi01040531	ISS1:1OF1	p32218_1	17/01/2013	p32218_1.cpl	NO
116	wi00897250	ISS1:1OF1	p31127_1	17/01/2013	p31127_1.cpl	NO
117	wi01042285	ISS1:1OF1	p32230_1	17/01/2013	p32230_1.cpl	YES
118	wi01020043	ISS1:1OF1	p32055_1	17/01/2013	p32055_1.cpl	NO
119	wi01006811	ISS1:1OF1	p31967_1	17/01/2013	p31967_1.cpl	YES
120	wi01038128	ISS1:1OF1	p32208_1	17/01/2013	p32208_1.cpl	NO
121	wi01003384	ISS1:1OF1	p31479_1	17/01/2013	p31479_1.cpl	NO
122	wi00967514	ISS1:1OF1	p31351_1	17/01/2013	p31351_1.cpl	NO
123	wi01039718	ISS1:1OF1	p32279_1	17/01/2013	p32279_1.cpl	YES
124	wi01003814	ISS1:1OF1	p31940_1	17/01/2013	p31940_1.cpl	NO
MDP>LAST SUCCESSFUL MDP REFRESH :2013-01-14 20:19:30(Local Time)						
MDP>USING DEPLIST ZIP FILE DOWNLOADED :2013-01-11 11:29:20(est)						

©2013 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.