



**Avaya Branch Gateways 6.3.5**  
**(build 35.8.0)**  
Release Notes

Issue 1  
May 05, 2014

© 2014 Avaya Inc.  
All Rights Reserved.

#### Notice

While reasonable efforts were made to ensure that the information in this document was complete and accurate at the time of printing, Avaya Inc. can assume no liability for any errors. Changes and corrections to the information in this document may be incorporated in future releases.

#### Documentation disclaimer

"Documentation" means information published by Avaya in varying mediums which may include product information, operating instructions and performance specifications that Avaya generally makes available to users of its products. Documentation does not include marketing materials.

Avaya Inc. is not responsible for any modifications, additions, or deletions to the original published version of this documentation unless such modifications, additions, or deletions were performed by Avaya. Customer and/or End User agree to indemnify and hold harmless Avaya, Avaya's agents, servants and employees against all claims, lawsuits, demands and judgments arising out of, or in connection with, subsequent modifications, additions or deletions to this documentation to the extent made by the Customer or End User.

#### Link disclaimer

Avaya Inc. is not responsible for the contents or reliability of any linked Web sites referenced elsewhere within this documentation, and Avaya does not necessarily endorse the products, services, or information described or offered within them. We cannot guarantee that these links will work all of the time and we have no control over the availability of the linked pages.

#### Warranty

Avaya Inc. provides a limited warranty on this product. Refer to your sales agreement to establish the terms of the limited warranty. In addition, Avaya's standard warranty language, as well as information regarding support for this product, while under warranty, is available through the following Web site:

<http://www.avaya.com/support>

Please note that if you acquired the Product(s) from an authorized Avaya reseller outside of the United States and Canada, the warranty is provided to you by said Avaya reseller and not by Avaya.

#### Copyright

Except where expressly stated otherwise, no use should be made of materials on this site, the Documentation, Software, or Hardware provided by Avaya. All content on this site, the documentation and the Product provided by Avaya including the selection, arrangement and design of the content is owned either by Avaya or its licensors and is protected by copyright and other intellectual property laws including the sui generis rights relating to the protection of databases. You may not modify, copy, reproduce, republish, upload, post, transmit or distribute in any way any content, in whole or in part, including any code and software unless expressly authorized by Avaya. Unauthorized reproduction, transmission, dissemination, storage, and or use without the express written consent of Avaya can be a criminal, as well as a civil offense under the applicable law.

#### Avaya support

Avaya provides a telephone number for you to use to report problems or to ask questions about your product. The support telephone number is 1-800-242-2121 in the United States. For additional support telephone numbers, see the Avaya Web site:

<http://www.avaya.com/support>

#### Third Party Components

Certain software programs or portions thereof included in the Product may contain software distributed under third party agreements ("Third Party Components"), which may contain terms that expand or limit rights to use certain portions of the Product ("Third Party Terms"). Information regarding distributed Linux OS source code (for those Products that have distributed the Linux OS source code), and identifying the copyright holders of the Third Party Components and the Third Party Terms that apply to them is available on the Avaya Support Web site: <http://support.avaya.com/Copyright>.

#### Preventing Toll Fraud

"Toll Fraud" is the unauthorized use of your telecommunications system by an unauthorized party (for example, a person who is not a corporate employee, agent, subcontractor, or is not working on your company's behalf). Be aware that there can be a risk of Toll Fraud associated with your system and that, if Toll Fraud occurs, it can result in substantial additional charges for your telecommunications services.

#### Avaya Toll Fraud Intervention

If you suspect that you are being victimized by Toll Fraud and you need technical assistance or support, call Technical Service Center Toll Fraud Intervention Hotline at +1-800-643-2353 for the United States and Canada. For additional support telephone numbers, see the Avaya Support Web site: <http://support.avaya.com> Suspected security vulnerabilities with Avaya

products should be reported to Avaya by sending mail to: [securityalerts@avaya.com](mailto:securityalerts@avaya.com).

#### Trademarks

The trademarks, logos and service marks ("Marks") displayed in this site, the Documentation and Product(s) provided by Avaya are the registered or unregistered Marks of Avaya, its affiliates, or other third parties. Users are not permitted to use such Marks without prior written consent from Avaya or such third party which may own the Mark. Nothing contained in this site, the Documentation and Product(s) should be construed as granting, by implication, estoppel, or otherwise, any license or right in and to the Marks without the express written permission of Avaya or the applicable third party.

Avaya is a registered trademark of Avaya Inc.

All non-Avaya trademarks are the property of their respective owners.

#### Downloading Documentation

For the most current versions of Documentation, see the Avaya Support

Web site: <http://support.avaya.com>.

#### Contact Avaya Support

Avaya provides a telephone number for you to use to report problems or to ask questions about your Product. The support telephone number is 1-800-242-2121 in the United States. For additional support telephone numbers, see the Avaya Web site: <http://support.avaya.com>.

## Contents

Changes Delivered to Branch Gateways 6.3.5 (build 35.8.0) . . . . .	5
Product Support Notices . . . . .	5
New Features added to Branch Gateways 6.3.5 (build 35.8.0) . . . . .	6
Fixed Issues in Branch Gateways 6.3.5 (build 35.8.0). . . . .	7
Known Issues in Branch Gateways 6.3.5 (build 35.8.0) . . . . .	7
Technical Support . . . . .	9



# Changes Delivered to Branch Gateways

## 6.3.5 (build 35.8.0)

---

### Product Support Notices

Some problems are also documented as Product Support Notices (PSN). The PSN number defines the related document and appears in the Problem column in the tables.

To read the PSN description online:

1. Go to the Avaya support site at <http://support.avaya.com>.
2. Click **Product Notices**.
3. Click **Product Support Notices**.
4. Type the last four digits of the PSN number into your web browser's "Find on Page" function to search the page for a link to the PSN.
5. Click the PSN title link to open the PSN.

## New Features added to Branch Gateways 6.3.5 (build 35.8.0)

**Table 1: New Features added to Branch Gateways 6.3.5 (build 35.8.0)**

Platform	Feature
G430	<p>Support added for the new MP120 DSP on the G430 to provide 120 VoIP channel capacity and to support V.150 features. The G430 now supports a maximum of 120 VoIP Channels.</p> <p>Note that the onboard DSP present on G430v1 gateways will be disabled whenever an MP120 is installed. G430v2 gateways with a pre-installed MP120 do not have an onboard DSP.</p>
G450	<p>Support added for the new G450 Supervisor board CS vintage 3 which uses a newer Ethernet switch and is compatible with all previous hardware vintages.</p> <p>The G450 Supervisor board CS vintage 3 requires Communication Manager 5.2.1 (SP 16) or higher and it requires the following BGW firmware versions to operate:</p> <ul style="list-style-type: none"> <li>• 5.2.1: version 30.28.0 (or later)</li> <li>• 6.3.1: version 34.6.0 (or later)</li> <li>• 6.3.5: version 35.8.0 (or later)</li> </ul> <p>Gateway firmware prior to the BGW versions listed are incompatible with G450 Supervisor board CS vintage 3 and will fail to download.</p> <p>Release 35.8.0 is backward compatible on older G450 hardware (G450 Supervisor board CS vintage 1, G450 Supervisor board CS vintage 2).</p>
G430, G450	<p>Support added for Crisis Tone used by Communication Manager's Crisis Alert Monitoring feature. For more information about this feature, see <i>Avaya Aura® Communication Manager Feature Description and Implementation</i>, 555-245-205.</p>

## Fixed Issues in Branch Gateways 6.3.5 (build 35.8.0)

This release includes the following fixed issues.

**Table 2: Fixed Issues in Branch Gateways 6.3.5 (build 35.8.0)**

Problem	Keywords	Workaround
<b>G430, G450</b> After a reboot, a gateway that immediately reconnects to an ESS without first connecting to a primary Communication Manager will now provide the maximum number of voip channels available on the gateway. In prior releases, a G450 with 320 VoIP channels only provided 240 channels if it reconnected to an ESS without first connecting to a primary Communication Manager. Similarly, a G430 with 105 VoIP channels only provided 100 VoIP channels.	130177	
<b>G430, G450</b> On rare occasions, some gateway CLI commands would lock-up and not complete if Link Layer Discovery Protocol (LLDP) is enabled.	130147	

## Known Issues in Branch Gateways 6.3.5 (build 35.8.0)

This release includes the following known issues.

**Table 3: Known Issues in Branch Gateways 6.3.5 (build 35.8.0)**

Problem	Keywords	Workaround
<b>G430, G450</b> This Branch Gateway version does not support multiple IPv6 VLAN interfaces.		Use single VLAN interface with IPv6.
<b>G430, G450</b> EM_WEB doesn't work via dial in session (usb modem).	090790	Use other interfaces for this types of connection.





# Technical Support

Support for Communication Manager is available through Avaya Technical Support.

If you encounter trouble with Communication Manager:

1. Retry the action. Carefully follow the instructions in written or online documentation.
2. Check the documentation that came with your hardware for maintenance or hardware-related problems.
3. Note the sequence of events that led to the problem and the exact messages displayed. Have the Avaya documentation available.
4. If you continue to have a problem, contact Avaya Technical Support by:
  - Logging in to the Avaya Technical Support Web site <http://www.avaya.com/support>
  - Calling or faxing Avaya Technical Support at one of the telephone numbers in the [Support Directory](#) listings on the Avaya support Web site.

You may be asked to email one or more files to Technical Support for analysis of your application and its environment.

**Note:**

If you have difficulty reaching Avaya Technical Support through the above URL or email address, please go to <http://www.avaya.com> for further information.

When you request technical support, provide the following information:

- Configuration settings, including Communication Manager configuration and browser settings.
- Usage scenario, including all steps required to reproduce the issue.
- Screen shots, if the issue occurs in the Administration Application, one-X Portal, or one-X Portal Extensions.
- Copies of all logs related to the issue.
- All other information that you gathered when you attempted to resolve the issue.



**Tip:**

Avaya Global Services Escalation Management provides the means to escalate urgent service issues. For more information, see the [Escalation Contacts](#) listings on the Avaya Web site.

For information about patches and product updates, see the Avaya Technical Support Web site <http://www.avaya.com/support>.

