



Intuity™ Messaging Solutions Integration with System 75, DEFINITY®

Generics 1 & 3, and R5/6 Addendum:
Centralized Voice Mail Installation

585-310-257ADD
Comcode 108780396
Issue 1-2
April 2000

Disclaimer

Intellectual property related to this product (including trademarks) and registered to Lucent Technologies Inc. has been transferred or licensed to Avaya Inc.

Any reference within the text to Lucent Technologies Inc. or Lucent should be interpreted as references to Avaya Inc. The exception is cross references to books published prior to April 1, 2001, which may retain their original Lucent titles.

Avaya Inc. formed as a result of Lucent's planned restructuring, designs builds and delivers voice, converged voice and data, customer relationship management, messaging, multi-service networking and structured cabling products and services. Avaya Labs is the research and development arm for the company.

Copyright © 2000, Lucent Technologies
All Rights Reserved
Printed in U.S.A.

Notice

Every effort was made to ensure that the information in this book was complete and accurate at the time of printing. However, information is subject to change.

Your Responsibility for Your System's Security

Toll fraud is the unauthorized use of your telecommunications system by an unauthorized party, for example, persons other than your company's employees, agents, subcontractors, or persons working on your company's behalf. Note that there may be a risk of toll fraud associated with your telecommunications system and, if toll fraud occurs, it can result in substantial additional charges for your telecommunications services.

You and your system manager are responsible for the security of your system, such as programming and configuring your equipment to prevent unauthorized use. The system manager is also responsible for reading all installation, instruction, and system administration documents provided with this product in order to fully understand the features that can introduce risk of toll fraud and the steps that can be taken to reduce that risk. Lucent Technologies does not warrant that this product is immune from or will prevent unauthorized use of common-carrier telecommunication services or facilities accessed through or connected to it. Lucent Technologies will not be responsible for any charges that result from such unauthorized use.

Lucent Corporate Security

Whether or not immediate support is required, all toll fraud incidents involving Lucent products or services should be reported to Lucent Corporate Security at 1 800 821-8235. In addition to recording the incident, Lucent Corporate Security is available for consultation on security issues, investigation support, referral to law enforcement agencies, and educational programs.

Lucent Technologies Fraud Intervention

If you *suspect that you are being victimized* by toll fraud and you need technical support or assistance, call the Lucent Technologies National Customer Care Center Toll Fraud Intervention Hotline at 1 800 643-2353.

Federal Communications Commission Statement

Part 15: Class A Statement. This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

Part 68: Network Registration Number. This equipment is registered with the FCC in accordance with Part 68 of the FCC Rules. It is identified by an FCC registration number.

Part 68: Answer-Supervision Signaling. Allowing this equipment to be operated in a manner that does not provide proper answer-supervision signaling is in violation of Part 68 Rules. This equipment returns answer-supervision signals to the public switched network when:

- Answered by the called station
- Answered by the attendant
- Routed to a recorded announcement that can be administered by the CPE user

This equipment returns answer-supervision signals on all DID calls forwarded back to the public switched telephone network. Permissible exceptions are:

- A call is unanswered
- A busy tone is received
- A reorder tone is received

Canadian Department of Communications (DOC)

Interference Information

This digital apparatus does not exceed the Class A limits for radio noise emissions set out in the radio interference regulations of the Canadian Department of Communications.

Le Présent Appareil Numérique n'émet pas de bruits radioélectriques dépassant les limites applicables aux appareils numériques de la class A prescrites dans le règlement sur le brouillage radioélectrique édicté par le ministère des Communications du Canada.

Trademarks

AUDIX, DEFINITY, MERLIN, and MERLIN LEGEND are registered trademarks of Lucent Technologies, Inc.

Intuity, Lucent, Lucent Technologies, and ProLogix are trademarks of Lucent Technologies, Inc.

UNIX is a registered trademark of UNIX Systems Laboratories, Inc.

UnixWare is a trademark of the Santa Cruz Operation, Inc.

VT100 is a trademark of Digital Equipment Corporation.

Ordering Information

Call: Lucent Technologies Publications Center
Voice 1 800 457-1235 International Voice 317 322-6791
Fax 1 800 457-1764 International Fax 317 322-6699

Write: Lucent Technologies Publications Center
2855 N. Franklin Road
Indianapolis, IN 46219

Order: Document No. 585-310-257add
Comcode 108780396
Issue 1-2, April 2000

You can be placed on a standing order list for this and other documents you may need. Standing order will enable you to automatically receive updated versions of individual documents or document sets, billed to account information that you provide. For more information on standing orders, or to be put on a list to receive future issues of this document, contact the Lucent Technologies Publications Center.

Warranty

Lucent Technologies provides a limited warranty on this product. Refer to the "Limited Use Software License Agreement" card provided with your package.

European Union Declaration of Conformity

Lucent Technologies Business Communications Systems declares that the equipment specified in this document conforms to the referenced European Union (EU) Directives and Harmonized Standards listed below:

EMC Directive 89/336/EEC

Low-Voltage Directive 73/23/EEC



The "CE" mark affixed to the equipment means that it conforms to the above directives.

Comments

To comment on this document, send an email to octeltechpubs@lucent.com or call +303-538-9625 to send a fax or leave a voice message.

Acknowledgment

This document was prepared by Technical Publications, Lucent Technologies, Denver, CO and Columbus, OH.

Purpose	1
Introduction	1
What is CVM-IMC?.....	1
Requirements	2
Before You Start	3
Installation Checklist	4
Installation Tasks	5
Configure the Switch Network	5
Reserve the Switch Voice Port for MWI.....	5
Install the Lucent Intuity System.....	6
Verify Switch Settings on the Lucent Intuity System.....	7
Set the MWI Indicators.....	8
Determine the Active Channels to Reassign.....	9
Assign the Last Active Ports.....	10
Update Automated Attendant Routing	12
Set the Dial Plan	13
Test the Installation.....	14
Troubleshooting	15

Installing DEFINITY CVM – IMC

Purpose

The purpose of this addendum is to provide basic information about DEFINITY® Centralized Voice Mail–Interswitch Mode Code (CVM–IMC), installation instructions, and administration instructions for integrating a Lucent Intuity™ Release 4 or Release 5 system into the network.

Throughout this document, you may see references to either Release 4 or Release 5 Lucent Intuity™ system procedures. If no difference is presented, assume that the information applies to both releases.


Introduction

This section includes a description of the feature, requirements for the Lucent Intuity installation, and requirements of the feature.

What is CVM–IMC?

Centralized Voice Mail–Interswitch Mode Code provides customers with the ability to network together a number of small switches that can share one Lucent Intuity voice mail system. The feature uses mode code protocol for call transfer and communications. The set of disparate switches are networked to one switch hub, which then provides call transfer ability to the Lucent Intuity.

Figure 1-1. DEFINITY R8.3 Network Configuration Example



The switches that can be integrated with DEFINITY R8.2 CVM–IMC include:

- DEFINITY ECS R8.2
- ProLogix™ R3
- DEFINITY BCS Issue 6

DEFINITY R8.3 CVM–IMC adds networking with these switches:

- MERLIN™ MAGIX
- MERLIN LEGEND® R6.0 or 7.1

You can network to a Lucent Intuity Release 4.4 or Release 5 system.

Requirements

The CVM–IMC integration has these requirements:

- The system only operates with a DEFINITY ECS Release 8.2, ProLogix R3, or DEFINITY BCS Issue 6 as the hub or as endpoints. Release 8.3 will also support MERLIN LEGEND or MERLIN MAGIX systems as endpoints.
- The network maximum capacity is 10 switches and 450 mailboxes.
- The switch network must be set up using mode code transfers.

- The switch network must be set up in a star configuration. Linear or tandem connections are not supported.
- The switch network requires ISDN-PRI trunks with D-Channel between switches.
- The network must use uniform dialing plan (UDP).
 - If the switch network is all DEFINITY systems, either 4 or 5 digit dial plans can be used.
 - If MERLIN LEGEND or MERLIN MAGIX systems are used in a DEFINITY system network, a 4 digit dial plan is required.
- The Lucent Intuity system must be a MAP/5P Release 4.4 or Release 5.
- On the Lucent Intuity system, the last active port on each voice card must be reserved for the message waiting indicator (MWI) interface.
- MWI ports cannot be in the hunt group.

Before You Start

Before starting to install the CVM–IMC, complete these items:

- Confirm that the Sales and Design Support Center (SDSC) has completed their design for the installation.
- Integrate the switch systems before starting the Lucent Intuity integration. The switch integrations must be working properly before the calls can be transferred to the Lucent Intuity system. See “Configure the Switch Network” on page 1-5 for a list of documents to use to set up the network.

Installation Checklist

Follow the steps in Table 1-1 to complete the CVM–IMC installation.

Table 1-1. CVM–IMC Installation Checklist

Task	Page	✓
1. Configure the Switch Network.	page 1-5	
2. Reserve the Switch Voice Port for MWI	page 1-5	
3. Install the Lucent Intuity System.	page 1-6	
4. Verify Switch Settings on the Lucent Intuity System.	page 1-7	
5. Set the MWI Indicators.	page 1-8	
6. Determine the Active Channels to Reassign.	page 1-9	
7. Assign the Last Active Ports.	page 1-10	
8. Update Automated Attendant Routing	page 1-12	
9. Set the Dial Plan	page 1-13	
10. Test the Installation	page 1-14	
11. Troubleshooting: complete any adjustments that may be required.	page 1-15	

Installation Tasks

This section includes the actual tasks to complete to install DEFINITY CVM–IMC. Follow these steps in order.

Configure the Switch Network

The switch network must be working properly using a mode code integration before connecting the Intuity AUDIX system to the CVM–IMC network. Given the complexity of the configuration and the possible configuration options, any steps for completing the integration must come from the respective documentation. These documents include:

- DEFINITY ECS R8.2 Administration for Network Connectivity, 555-233-504
- DEFINITY ECS R8.2 Administrator's Guide, 555-233-506
- MERLIN LEGEND and MERLIN MAGIX Communications System, see the respective Network Reference

Reserve the Switch Voice Port for MWI

A CVM-IMC integration uses mode code transfers. Since this method is slower than others, the last extension on each voice port circuit card on the switch must be reserved for MWI updates by excluding it from the hunt group. Otherwise, MWI updates must often wait for a port. Reserving one port on each card allows MWI updates to occur without delay.

Assign only the first five extensions of each voice port circuit card to a hunt group on the hub switch. If the last extension is not part of the hunt group, the switch will not use it to route traffic to the Intuity.

Note:

If a customer uses less than a full voice port circuit card, skip any unused ports and use the last port on that card for MWI updates.

For more information about assigning extensions in hunt groups, see the documentation for your switch listed in “Configure the Switch Network” above.

Install the Lucent Intuity System.

If this is a new installation, follow existing documentation to install the Lucent Intuity system. Different documents exist for Release 4 and for Release 5.

For Release 4.4 systems, use any of these documents that you may find helpful:

- Intuity Messaging Solutions Release 4 MAP/5P System Installation (585-310-185)
- Intuity Integration with System 75 and DEFINITY Communications System Generic 1 and Generic 3 (585-310-214)
- Intuity Messaging Solutions Integration with System 75, DEFINITY Generics 1&3, and R5/6 (585-310-257)
- Intuity Messaging Solutions Integration with MERLIN LEGEND (585-310-255)

For Release 5 systems, use any of these documents that you may find helpful:

- Intuity Messaging Solutions Release 5 Installation for New Systems (585-313-119)
- Intuity Messaging Solutions Getting Connected (585-313-703)
- Intuity Messaging Solutions Release 5 Documentation CD-ROM (585-313-803)
- Intuity Messaging Solutions Release 5 Documentation for Technicians (585-313-807)
- Intuity Messaging Solutions Integration with MERLIN LEGEND (585-310-255)
- Intuity Messaging Solutions Integration with System 75, DEFINITY Generics 1&3, and R5/6 (585-310-257)

Verify Switch Settings on the Lucent Intuity System

This task confirms that the Lucent Intuity system is using the correct switch integration. Select the procedure for your system:

- “Intuity AUDIX Release 4.4” on this page
- “Intuity AUDIX Release 5” on page 1-7

Intuity AUDIX Release 4.4

To verify the switch integration on an Intuity AUDIX 4.4 system:

1. Start at the Lucent Intuity Main Menu and select:

```
Switch Interface Administration
Switch Selection
```

The system displays Figure 1-2.

Figure 1-2. Switch Selection Screen

The screenshot shows a terminal window titled "Switch Selection". Inside the window, there are two lines of text: "Country : UNITED STATES" and "Switch : DEFINITY MODE CODE". The text is displayed in a monospaced font on a dark background.

2. Confirm that “DEFINITY MODE CODE” is displayed in the Switch field, then do one of the following:
 - If DEFINITY MODE CODE is displayed, continue with “Set the MWI Indicators” on page 1-8.
 - If another switch integration is displayed, contact the Remote Support Center.

The existing integration must be unloaded and the SWINset Serial-Inband Switch Integration must be loaded. After this work is completed, continue with “Set the MWI Indicators”.

Intuity AUDIX Release 5

To verify the switch integration on an Intuity AUDIX 5 system:

1. Start at the Lucent Intuity Main Menu and select:

```
Feature Options
```

The system displays Figure 1-3.

Figure 1-3. Feature Options Screen

Feature Options (Read Only)		
Feature Options Available	Current	Max
Audix Application	ON	N/A
DCS	OFF	N/A
Enhanced-List Application	OFF	N/A
Fax	ON	N/A
High speed digital ports	0	12
Internet Messaging Application	OFF	N/A
LDAP Directory	OFF	N/A
Low speed digital ports	0	12
Lucent Voice Director Sessions	0	64
Lucent Voice Director Size	0	20000
Max Number of IMAPI Sessions	64	96
Multilingual	ON	N/A
Number of Mailboxes Purchased	15000	20000
TCPIP digital ports	0	12
Text-to-Speech Sessions	4	4
Trusted Servers	16	64
hours_of_speech	100	175
voice_ports	6	6

2. Press F1 Acknowledge to clear the message on the screen.
3. Press F7 Switch Select.

The system displays Figure 1-2.

4. Confirm that “DEFINITY MODE CODE” is displayed in the Switch field, then do one of the following:
 - If DEFINITY MODE CODE is displayed, continue with “Set the MWI Indicators”.
 - If another switch integration is displayed, contact the Remote Support Center.

The existing integration must be unloaded and the SWINset Serial-Inband Switch Integration must be loaded. After this work is completed, continue with “Set the MWI Indicators”.

Set the MWI Indicators

The message waiting indicators must be set correctly on the Lucent Intuity system to work with the switch integration.

To set the MWI indicators:

1. Start at the Lucent Intuity Main Menu and select:

```
Switch Interface Administration
  Call Data Interface Administration
    MWI Administration
      Device Assignment
```

The system displays Figure 1-4.

Figure 1-4. Device Assignment Screen

2. Enter **1** in the Switch Number field.
3. Enter **3** in the Device ID field.
4. Press F3 Save.
5. Press F6 Cancel twice.
6. Continue with “Determine the Active Channels to Reassign”.

Determine the Active Channels to Reassign

The last active channel on each voice circuit card must be assigned to a separate group for use by the message waiting indicator. Use this procedure to determine which channels to reassign.

To determine the active channels to reassign:

1. Start at the Lucent Intuity Main Menu and select:

```
Voice System Administration
Voice Equipment
```

The system displays Figure 1-5.

Figure 1-5. Display Voice Equipment Screen

Display Voice Equipment									
CD	PT	CHN	STATE	STATE-CHNG-TIME	SERVICE-NAME	PHONE	GROUP	OPTS	TYPE
CARD	0	STATE: Inserv		CLASS: Analog(TR)		O.S.INDEX: 0			
		NAME: AYC10		OPTIONS: master1,no tdm,tt					
		FUNCTION: TipRing							
0.0	0	Inserv	Mar 22 14:28:07	AUDIX	88001	2	talk	IVC6	
0.1	1	Inserv	Mar 22 14:28:07	AUDIX	88002	2	talk	IVC6	
0.2	2	Inserv	Mar 22 14:28:07	AUDIX	88003	2	talk	IVC6	
0.3	3	Inserv	Mar 22 14:28:07	AUDIX	88004	2	talk	IVC6	
0.4	4	Inserv	Mar 22 14:28:07	AUDIX	88005	2	talk	IVC6	
0.5	5	Inserv	Mar 22 14:28:07	AUDIX	88006	2	talk	IVC6	
oo									

2. Check the CD .PT column for the number of voice port circuit cards.

The voice port circuit card numbering starts at zero and increments by one through to five. For example, if a system has two voice port circuit cards, the first card's ports would be numbered 0.0, 0.1, 0.2, 0.3, 0.4, and 0.5. The second card's ports would be numbered 1.0, 1.1, 1.2, 1.3, 1.4, and 1.5.

The last active port on each card must be reassigned from group 2 to group 3 for use as the MWI port.

3. Record the card, port and group information in Table 1-2.

Table 1-2. MWI Port Old and New Group Assignments

Card	Last Active Port	Old Group	New Group
1			3
2			3
3			3

4. Continue with "Assign the Last Active Ports".

Assign the Last Active Ports

After determining the ports to reassign, use this procedure to complete the reassignment.

To reassign the last active ports:

1. On the Display Voice Equipment Screen (Figure 1-5), press F8 Actions, then select:

```
Unassign
Channels from Groups
```

The system displays Figure 1-6.

Figure 1-6. Unassign Channels from Groups Screen

2. Select the group to change from Table 1-2.

3. In the Channels field, enter **5** (or the number for the last active channel on this voice port circuit card).
4. In the Groups field, enter **2**.
5. Press F3 Save.

The system displays the message:

```
Channel X deleted from equipment group(s) 2  
Hit acknowledge key to continue
```

Where X is the last active channel on the voice port circuit card.

6. Press F1 Acknowledge.
7. Press F6 Cancel twice.
8. From the Actions menu, select:

```
Assign/Change  
Channels to Groups
```

9. In the Channels field, enter the same channel number as in Step 3.
10. In the Groups field, enter **3**.
11. Press F3 Save.

The system displays the message:

```
Channel X is assigned to equipment group 3  
Hit acknowledge key to continue
```

Where X is the last active channel on the voice port circuit card.

12. Press F1 Acknowledge.
13. Press F6 Cancel three times.
14. Verify that the last active channel is changed to 3.
15. Determine the next step:
 - If there are more channels to reassign, go back to step 2 for the next channel.
 - If there are no more channels to reassign, continue with step 16.
16. Press F6 Cancel twice to return to the Intuity Main Menu.
17. Continue with “Update Automated Attendant Routing” on page 1-12.

Update Automated Attendant Routing

Use this procedure if the switch network includes a MERLIN LEGEND or MERLIN MAGIX. If the network includes only DEFINITY systems, skip to “Set the Dial Plan” on page 1-13.

Normally, automated attendant routing does not require any modifications from default settings. However, CVM-IMC requires that the extension length be changed from the default Merlin Legend length to four digits, so the Intuity AUDIX auto-attendant routing table must be updated to include the changed trunk numbering.

To update the auto-attendant routing table:

1. Start at the Lucent Intuity Main Menu and select:

AUDIX Administration

2. At the command line, enter:

```
change auto-attendant-routing routing-table
```

The system displays Figure 1-7.

Figure 1-7. Auto-Attendant Routing Table

```
change auto-attend-routing routing-table
```

Page 1 of 2

AUTO-ATTENDANT ROUTING TABLE					
Routing Table Administration					
Incoming Called Number	Business Schedule	Holiday Schedule	Day Service Mailbox	Night Service Mailbox	Alternate Service Mailbox
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

```
Command aborted
```

```
enter command: change auto-attend-routing routing-table
```

3. Update the auto-attendant routing table to include the MERLIN LEGEND dialing plan and other system settings.

For more information about administering the auto-attendant routing screen, see:

- Lucent Intuity Release 5 systems, “Administration” on R5 Documentation CD (585-313-803)
- INTUITY Messaging Solutions Release 4 Administration, 585-310-564, Issue 2

4. Continue with “Set the Dial Plan”.

Set the Dial Plan

Verify that the range of Intuity AUDIX extensions is sufficient to include all subscribers on all switches in the network.

To assign the channels:

1. Start at the Lucent Intuity Main Menu and select:

```
Switch Interface Administration
Call Data Interface Administration
System Translation Administration
Dial Plan Administration
```

The system displays Figure 1-8.

Figure 1-8. Dial Plan Administration Screen

The screenshot shows the 'Dial Plan Translation' screen, labeled 'Screen 1 of 5'. It displays a table with columns for 'Switch Prefix', 'Switch Start Ext.', 'Switch End Ext.', 'INTUITY Prefix', 'Switch Number', and 'Remote [Y/N]'. The 'INTUITY Extension Length' is set to 4, and the 'Switch Network Access Code' is 9. The first row shows a switch with prefix 1, start extension 1000, and end extension 5999. The remaining rows are empty.

	Switch Prefix	Switch Start Ext.	Switch End Ext.	INTUITY Prefix	Switch Number	Remote [Y/N]
1		1000	5999		1	N
2						
3						
4						
5						
6						
7						
8						
9						
10						

2. Verify that the Switch Start Ext. and Switch End Ext. fields range from zeros to nines for the extension length of the CVM–IMC network.

For example, if the Intuity Extension Length is 4, then the range of extensions would be 0000 to 9999.

Some customers may require that specific extension ranges be used instead of one range that includes all extensions. This

method will also work properly, but is not necessary for this integration.



CAUTION:

If the customer requires that specific extension ranges be entered, the Switch Number must be “1” for every range. Any range with a switch number other than 1 will not have calls transferred to it.

3. Do one of the following:
 - If the range is not correct, tab to the respective fields and change the entries.
 - If the range is correct, continue with “Test the Installation” on page 1-14.

Test the Installation

Confirm that the installation is correct by placing test calls through the network to leave and retrieve messages.

In general, follow these steps:

1. Place a call from inside the network that goes to voicemail.
2. Place a call from outside the network that goes to voicemail.
3. Verify that the MWI lamp turns on.
4. Retrieve the in-network message.
5. Retrieve the out-of-network message.
6. Verify that the MWI lamp turns off.
7. Return to step 1 and follow the same procedure on each switch in the network.

Troubleshooting

If testing shows that some aspect of the system isn't working correctly, use Table 1-3 to find possible solutions.

Table 1-3. Possible Trouble Areas

Problem	Check if:	Action
Calls to station on hub switch do not cover to voicemail	Station has coverage path set up to voice mail.	Add coverage path.
	Station has mailbox on Intuity AUDIX system.	Add mailbox.
	Mode codes on DEFINITY hub match the Intuity AUDIX system.	Make codes on both switch hub and Intuity AUDIX match.
	Mode codes are being received on the Intuity AUDIX system.	Change ports on the hub from "2500" to "VMI".
Calls to remote system do not cover to correct mailbox.	ISDN-PRI trunk is set to "private."	Set trunk to private.
	Signaling group and trunk group between remote and hub are in-service and set to subscriber.	On the DS1 form on the switch hub, set the Interface field to "network". In the same field on the endpoint, set the field to "user".
	Remote site has correct Remote VMS Hunt group.	Add correct hunt group.

(1 of 2)

Table 1-3. Possible Trouble Areas

Problem	Check if:	Action
MWI not being updated for stations on the hub switch.	Messages still in mailbox.	Clear messages, then call back to leave another message. Confirm that the MWI is updated properly. Check the activity log against the extension to see that the proper mode codes are being sent.
	LWC store and LWC cancel feature access codes match on the Intuity AUDIX.	Make the mode codes match. Check the mode codes on the switch and on the Intuity AUDIX. If necessary, change the entries on the Message Waiting Parameters screen on the Intuity AUDIX.
	Intuity AUDIX has an analog voice port that is assigned to MWI updates.	Dedicate the MWI port. See “Determine the Active Channels to Reassign” on page 1-9.
	MWI dedicated port is in the hunt group.	Remove the MWI port from the hunt group on the switch. See “Assign the Last Active Ports” on page 1-10.
	MWI access codes are being sent from the Intuity AUDIX.	Check the Switch Integration Log for whether the appropriate codes are being sent.
When the system is under load, some calls to Intuity AUDIX are un-integrated.	Switch is getting data to Intuity AUDIX before the call times out.	Contact the Remote Support Center.
	Mode codes are not defined properly.	Reselect the Switch and Country.  CAUTION: Reselecting the switch and country clears any custom settings from the switch integration and requires that they be reentered.

(2 of 2)