

Avaya Session Border Controller (ASBC) 10.2.1.2 Release Notes

© 2025 Avaya Inc. All Rights Reserved.

Notice

While reasonable efforts were made to ensure that the information in this document was complete and accurate at the time of printing, Avaya Inc. can assume no liability for any errors. Changes and corrections to the information in this document might be incorporated in future releases.

Documentation disclaimer

Avaya Inc. is not responsible for any modifications, additions, or deletions to the original published version of this documentation unless such modifications, additions, or deletions were performed by Avaya. Customer and/or End User agree to indemnify and hold harmless Avaya, Avaya's agents, servants and employees against all claims, lawsuits, demands and judgments arising out of, or in connection with, subsequent modifications, additions or deletions to this documentation to the extent made by the Customer or End User.

Link disclaimer

Avaya Inc. is not responsible for the contents or reliability of any linked Web sites referenced elsewhere within this documentation, and Avaya does not necessarily endorse the products, services, or information described or offered within them. We cannot guarantee that these links will work all the time and we have no control over the availability of the linked pages.

Warranty

Avaya Inc. provides a limited warranty on this product. Refer to your sales agreement to establish the terms of the limited warranty. In addition, Avaya's standard warranty language, as well as information regarding support for this product, while under warranty, is available through the Avaya Support Web site: http://support.avaya.com

License

USE OR INSTALLATION OF THE PRODUCT INDICATES THE END USER'S ACCEPTANCE OF THE TERMS SET FORTH HEREIN AND THE GENERAL LICENSE TERMS AVAILABLE ON THE AVAYA WEB SITE http://support.avaya.com/LicenseInfo/ ("GENERAL LICENSE TERMS"). IF YOU DO NOT WISH TO BE BOUND BY THESE TERMS, YOU MUST RETURN THE PRODUCT(S) TO THE POINT OF PURCHASE WITHIN TEN (10) DAYS OF DELIVERY FOR A REFUND OR CREDIT.

Avaya grants End User a license within the scope of the license types described below. The applicable number of licenses and units of capacity for which the license is granted will be one (1), unless a different number of licenses or units of capacity is specified in the Documentation or other materials available to End User. "Designated Processor" means a single stand-alone computing device. "Server" means a Designated Processor that hosts a software application to be accessed by multiple users. "Software" means the computer programs in object code, originally licensed by Avaya and ultimately utilized by End User, whether as stand-alone Products or pre-installed on Hardware. "Hardware" means the standard hardware Products, originally sold by Avaya and ultimately utilized by End User.

License type(s)

Concurrent User License (CU). End User may install and use the Software on multiple Designated Processors or one or more Servers, so long as only the licensed number of Units are accessing and using the Software at any given time. A "Unit" means the unit on which Avaya, at its sole discretion, bases the pricing of its licenses and can be, without limitation, an agent, port or user, an e-mail or voice mail account in the name of a person or corporate function (e.g., webmaster or helpdesk), or a directory entry in the administrative database utilized by the Product that permits one user to interface with the Software. Units may be linked to a specific, identified Server.

Copyright

Except where expressly stated otherwise, the Product is protected by copyright and other laws respecting proprietary rights. Unauthorized reproduction, transfer, and or use can be a criminal, as well as a civil, offense under the applicable law.

Third-party components

Certain software programs or portions thereof included in the Product may contain software distributed under third party agreements ("Third Party Components"), which may contain terms that expand or limit rights to use certain portions of the Product ("Third Party Terms"). Information identifying Third Party Components and the Third Party Terms that apply to them is available on the Avaya Support Web site:

http://support.avaya.com/ThirdPartyLicense/

Preventing toll fraud

"Toll fraud" is the unauthorized use of your telecommunications system by an unauthorized party (for example, a person who is not a corporate employee, agent, subcontractor, or is not working on your company's behalf). Be aware that there can be a risk of toll fraud associated with your system and that, if toll fraud occurs, it can result in substantial additional charges for your telecommunications services.

Avava fraud intervention

If you suspect that you are being victimized by toll fraud and you need technical assistance or support, call Technical Service Center Toll Fraud Intervention Hotline at +1-800-643-2353 for the United States and Canada. For additional support telephone numbers, see the Avaya Support Web site: http://support.avaya.com

Trademarks

Avaya and the Avaya logo are either registered trademarks or trademarks of Avaya Inc. in the United States of America and/or other jurisdictions. All other trademarks are the property of their respective owners.

Downloading documents

For the most current versions of documentation, see the Avaya Support Web site: http://support.avaya.com

Avaya support

Avaya provides a telephone number for you to use to report problems or to ask questions about your product. The support telephone number is 1-800-242-2121 in the United States. For additional support telephone numbers, see the Avaya Support Web site: http://support.avaya.com

Table of contents:

TABLE OF CONTENTS:	
OVERVIEW	
DOCUMENTATION FOR 10.2.1.0	
SOFTWARE DOWNLOADS	
MANDATORY PATCH BEFORE UPGRADING FROM 10.2.1.0 TO 10.2.1.2	
SUPPORTED UPGRADE PATHSUPPORTED PLATFORMS FOR UPGRADE	
LIST OF KNOWN ISSUES WITH WORKAROUNDS	8
LIST OF FIXED ISSUES	

Overview

This document provides information about the enhancements, upgrade support, platforms supported, software download information, list of fixed, known issues and workarounds in ASBC Release 10.2.1.2.

Documentation for 10.2.1.0

Title	Support Site Link
Avaya Session Border Controller Overview and Specification	https://support.avaya.com/css/public/documents/101092029
Deploying Avaya Session Border Controller on a Hardware Platform	https://support.avaya.com/css/public/documents/101092031
Deploying Avaya Session Border Controller on a Virtualized Environment Platform	https://support.avaya.com/css/public/documents/101092033
Deploying Avaya Session Border Controller on an Amazon Web Services Platform	https://support.avaya.com/css/public/documents/101092035
Deploying Avaya Session Border Controller on a Microsoft Azure Platform	https://support.avaya.com/css/public/documents/101092037
Deploying Avaya Session Border Controller on a Google Cloud Platform	https://support.avaya.com/css/public/documents/101092039
Upgrading Avaya Session Border Controller	https://support.avaya.com/css/public/documents/101092041
Administering Avaya Session Border Controller	https://support.avaya.com/css/public/documents/101092043
Maintaining and Troubleshooting Avaya Session Border Controller	https://support.avaya.com/css/public/documents/101092045
Working with Avaya Session Border Controller and Microsoft Teams	https://support.avaya.com/css/P8/documents/101088711
Working with Avaya Session Border Controller Multi- Tenancy	https://support.avaya.com/css/P8/documents/101088713
Working with Avaya Session Border Controller Geographic-Redundant Deployments	https://support.avaya.com/css/P8/documents/101088715
Avaya Session Border Controller Release Notes	https://support.avaya.com/css/public/documents/101093769
Avaya Session Border Controller Port Matrix	https://support.avaya.com/css/public/documents/101088607

Software Downloads

IMPORTANT NOTE:

Starting 10.2.1.1, licensing for Avaya Session Boarder Controller (ASBC) will only work with 10.1.3.1 and higher version of System Manager (SMGR) or Standalone WebLM (WebLM). If upgrading ASBC to 10.2.1.1 or later release, then the required order of upgrade is imperative i.e. SMGR and/or WebLM should be upgraded to 10.1.3.1 and higher first to ensure licensing for ASBC does not stop working.

- License Enforcing feature ensures that the system successfully acquires the required number of licenses before processing any calls. Any failure to obtain the appropriate license count due to connectivity issues or misconfiguration can lead to call failures or other operational disruptions.
- To avoid such issues, it is essential to perform a thorough precheck and assessment, and to follow the upgrade or release support documentation carefully. It's common for both static and dynamic licensing configuration.

Before upgrading ASBCE release to 10.2.1.x ensure the following:

- There are no connectivity issues between ASBC and the License Server.
- License acquisition is successful and without errors.

Failure to meet these prerequisites may result in service interruptions.

Every SBC must have licenses allocated under **Device Management>Devices> Edit device>licensing settings** form.

Software downloads are available at following links:

https://support.avaya.com/downloads/ https://plds.avaya.com

File Name	PLDS ID	MD5SUM	Remarks
sbce-10.2.1.2-105-25570- dafbc415f3ab105a0c11782b49ed0e40.tar.gz	SBCF0000401	dafbc415f3ab105a0c11782b 49ed0e40	Upgrade package for upgrade 10.2.1.2 release
			Note: 10.2.1.2 release is applicable for non-JITC customers only. JITC customers must not install this software.
sbce-10.2.1.2-105-25570- dafbc415f3ab105a0c11782b49ed0e40.tar.gz.asc	SRCF0000402	67d05f5d5a7469e976542e6 4fa3ed604	Signature file to be used to upgrade to 10.2.1.2 release
sbce-10.2.1.2-105-25570-signatures.tar.gz	SBCE0000403	729abd4ccf0e87792f8085d7 780174d0	Key Bundle to validate RPM signatures
sbce-10.2.1.2-105-25570_uberutility- 0b6fa2f53291c06ca460883db34896f6.tar.gz	SBCE0000404	_	Uberutility tool to clean disk space and work around fixes
sbce-10.2.1.2-105-25570.iso	NRC FUUUUU4US		ISO image for fresh install on VM and hardware in 10.2.1.2 release

Mandatory Patch Before Upgrading from 10.2.1.0 to 10.2.1.2

GUI based upgrade from SBC 10.2.1.0 to SBC 10.2.1.2 **mandates** installation of Hotfix4 on SBC 10.2.1.0 software (EMS only) before initiating upgrade.

Hotfix4 Details:

PLDS ID: SBCE0000396

• File Name: asbc_10.2.1.0-Hotfix-004-01.tar md5sum: 14f28a9a4d3d796d5cd53a9b49c00d2c

Procedure to install hotfix

Download Package name: asbc_10.2.1.0-Hotfix-004-01.tar

from PLDS and extract the files on your local system:

When extracted, the following files:

Hotfix compressed package file: asbc_10.2.1.0-Hotfix-004-01.tgz

Hotfix md5sum file: asbc_10.2.1.0-Hotfix-004-01.tgz.md5

Install Script: patchSBC

should show in a directory "asbc_10.2.1.0-Hotfix-004-01".

Hotfix Installation:

Hotfix installation is supported through Command line (CLI) only.

Use a secure copy utility (e.g., WinSCP) to upload the extracted files to the /home/ipcs/ directory of the EMS.

Note: Install script (patchSBC) will validate the checksum using the Hotfix md5sum file. Ensure the md5sum file is in the same directory as the Hotfix compressed package file.

Installation Procedure for EMS

STEP1: Login over SSH and gain root access.

STEP2: Run below commands to Install the Hotfix using the Install Script (patchSBC)

> /usr/local/ipcs/peon/venv/bin/python patchSBC -i /home/ipcs/asbc_10.2.1.0-Hotfix-004-01.tgz

STEP3: After the Hotfix installation has completed, you will be prompted with options to: Do you want to clean up temporary files? (yes/no):

If you provide yes. The files will be cleaned. This is a recommended option. Please use "no" incase if you see any errors on screen or to debug any issue observed. If option "no" is chosen, then it must be the user's responsibility to clean up installer files that are in "/usr/local/ipcs/temp" diretcory. Do you want to reboot the system now? (yes/no):

Press "no" to debug installation errors.

If the session timeout is reached before the installer can answer the prompts, just login again as the root user and issue "reboot" from the command line to finish the Hotfix installation process. Important Notes:

It is required to reboot the device after Hotfix installation. So, please make sure that you reboot the device.

Imp Note:

In case of disk space issues run "partitionmanager.py" and "sbc-diskspace-cleanup.py" scripts before initiating upgrade. For detailed procedure, follow Maintaining and Troubleshooting Avaya Session Border Controller guide.

Supported Upgrade Path

- 10.2.1.0 GA -> 10.2.1.2
- 10.2.1.1 GA -> 10.2.1.2

Notes:

- 1. ASBC 10.2.1.0(UEFI) allows direct upgrade to 10.2.1.2. All other SBC version/releases should be upgraded or migrated as appropriate to 10.2.1.0(UEFI) and then upgrade to 10.2.1.2.
- 2. Whenever upgrading or migrating from lower release, bring EMS and SBCs to same version and then upgrade/migrate to higher version. For example, if you are planning to upgrade your SBC from 10.2.1.0(UEFI) to 10.2.1.2, then first bring your EMS and SBCs to 10.2.1.0 GA build (as per the documented procedure), then upgrade to 10.2.1.2

Supported Platforms for Upgrade

The following platforms are supported for upgrading from releases listed in "Supported Upgrade Path":

- 1. Dell 3240
- 2. Dell R340

- 3. VMWARE ESXI Version 7.x/8.x
- 4. Dell R640 (ASP110 P3 and ASP110 P5)
- 5. Dell 660(A2 and A3)
- 6. Dell 360
- 7. VEP1425N
- 8. Azure, AWS, Nutanix, GCP

Note: VMware/ESXI version older than 7.0 is not supported.

List of Known Issues with Workarounds

Issue Summary	Workaround
506	Run the command: "sbceconfigurator.py generate-rest-credentials" for SBC and EMS
	2. Re-install key certificate
. •	we need to run below command on SBC's Run the command: " iptables -A MGMTPROTECT -p udp -m udpsource \$EmsAddressdport 161 -j SNMPBRUTE "

List of fixed issues

Key	Summary
AURORA-36089	auth.log and message log rotate failure intermittently and the log still wrote to auth.log.1 with old FD
AURORA-36081	Moving/Migrate EMS+SBCE to another EMS failed
AURORA-36052	Call Reconstruction for CS trunk in NG911 environment fail for certain SP, because that SP cannot handle reINVITE with Replaces
AURORA-36100	call drop in 15 sec in transcoding call, reboot/restart restore the service
AURORA-35019	SBC is only sending Agent side voice to the Recording Server In CBA (Call-back Assistance) scenario
AURORA-36063	SBC Failover with transcoding call in NG911 environment result in no audio
AURORA-36138	After handling reINVITE (with replaces header for call reconstruction) in NG911environment, SP/NGCS still reject the call as it has lower CSeq than the previous SUBSCRIBE msg in this dialog.
AURORA-36123	Hold/Unhold fails in Workplace when upgrade SBC/Aura to 10.x, due to user configured uppercase domain name in RW, causing SBC fail to add subid_ipcs
AURORA-35229	oampserver, turncontroller, logserver service keep on crashing and filled logs very quickly results outage with high CPU usage
AURORA-36051	SBC crash due to 2000K, in a shared control case with AAFD, when desk phone de-register and another client app is slow to respond.
AURORA-36117	ASBCE is not sending UUI (user-to-user) while generating invite after 2nd refer message
AURORA-35806	SBC remove SDP in a retransmitted 2000K after some shuffling, causing call to drop.
AURORA-36142	Disk partition is not correct in some setups
AURORA-36137	License compliance page is not working on 10.2.1.0 (Fresh install).
AURORA-35843	MS Dashboard misreports inbound vs outbound calls stats due to Contact header from Avaya
AURORA-36139	Call transfer (with refer handling enabled) call drop in 14s because SBC send a ACK to SP with corrupted From header