

Leap Second Impact Update for Avaya Products

Updated: 6/29/2015 v28						
Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
Engagement Solutions						
Avaya Aura® Communication Manager	5.2.1	EoMS - upgrade to newer release	NA	PSN020178u	http://support.avaya.com/css/P8/documents/101008265	
	6.0.1	No longer bugfix supported - NTP provided by System Platform so no RHEL kernel vulnerability - upgrade to newer release	NA			
	6.2	No longer bugfix supported - NTP provided by System Platform so no RHEL kernel vulnerability - upgrade to newer release	NA			
	6.3.x	NTP provided by System Platform so no RHEL kernel vulnerability				
Avaya Aura® Communication Manager Messaging	5.2.1	EoMS - upgrade to newer release	NA	CMM Support Page - PSN		
	6.0.1	EoMS - upgrade to newer release	NA			
	6.2	EoMS - upgrade to newer release	NA			
	6.3	Security Patch SSP6	NA			
Avaya Aura® Communication Manager Messaging - FM	6.0.1	EoMS - upgrade to newer release	NA	CMM Support Page - PSN		
	6.3	Security Patch SSP6	NA	CMM Support Page - PSN		
Avaya Aura® Session Manager	5.2	EoMS - upgrade to newer release. PSN will detail workarounds	NA	PSN004439u	http://support.avaya.com/css/P8/documents/101008204	
	6.0	No longer bugfix supported - upgrade to newer release. PSN will detail workarounds	NA			
	6.1	No longer bugfix supported - upgrade to newer release. PSN will detail workarounds	NA			
	6.2.x	PSN will detail workarounds	NA			
	6.3.x	Upgrade to 6.3.13, or PSN will detail workarounds	04/13/15	PSN004439		
	6.3.13	This release supports leap second	04/13/15	PSN004439		
Avaya Aura® System Manager	5.2 + latest SP	EoMS - upgrade to newer release	NA	NA	https://downloads.avaya.com/css/P8/documents/100169515	https://downloads.avaya.com/css/P8/documents/101009336
	6.0 SP1 + latest SP	No longer bugfix supported - upgrade to newer release	NA	NA		
	6.1	No longer bugfix supported - upgrade to newer release	NA	NA		
	6.2.x	Fix available starting 6.3.13	04/13/15	PCN1913S		
	6.3.x	Fix available starting 6.3.13	04/13/15	https://downloads.avaya.com/css/P8/documents/100169515		
	6.3.13	This release supports leap second	04/13/15			
WebLM (on VMware)	6.2 OVA	Fix available starting 6.3.13	04/13/15	PCN1943S	https://downloads.avaya.com/css/P8/documents/100173682	https://downloads.avaya.com/css/P8/documents/101009334
	6.3 OVA	Fix available starting 6.3.13	04/13/15			
	6.3.13	This release supports leap second	04/13/15			
Avaya Aura® Presence Services	6.1.5	No longer bugfix supported - upgrade to newer release.	NA	PSN029019u	https://downloads.avaya.com/css/P8/documents/101008742	
	6.2.6	Will be delivered as PS 6.2.6 Patch 3 (PRES-3890).	03/27/15	https://downloads.avaya.com/css/P8/documents/101008742		
Avaya Aura® Presence Services - SW Only Offer	6.2.6	Patch 3 for PS 6.2.6 will be applicable to all deployment methods of PS including the SW only offer.	03/27/15	PSN029019u	https://downloads.avaya.com/css/P8/documents/101008742	
Avaya Aura® Application Enablement Services	4.2	No longer supported but likely impacted. Recommend stop NTP service before June 30th and restart NTP service after July 1st.			https://downloads.avaya.com/css/P8/documents/101009241	
	5.2	No longer supported - no impact.				
	5.2.4	No	NA	PSN004417u		
	6.1.x	No	NA			
	6.2.x	No	NA			
	6.3.x	No	NA			
Avaya Aura® Application Enablement Services - Software Only offer	all releases	No need to provide any patch for software only because customers are maintaining OS for software only installation	NA			
Avaya Aura® System Platform	6.0	Not impacted by the leap second	NA	PSN027015u	http://support.avaya.com/css/P8/documents/101008455	
	6.2	Not impacted by the leap second	NA			
	6.3.x	RHEL kernel version has no vulnerability	NA			
Avaya Aura® Utility Services	6.1	No longer bugfix supported - upgrade to newer release	NA		http://support.avaya.com/css/P8/documents/101008455	
	6.2	No remediation required; upgrade to V6.3	NA			
	6.3	RHEL kernel version has no vulnerability	NA	PSN027015u		
G430/G450 Media Gateway	6.3.x	Will not require any changes for Leap second.	NA			
Avaya Aura® Solution for Midsize Enterprise	6.1	Remediate as advised for each Application	See Application			
	6.2	Remediate as advised for each Application	See Application			
	6.2.2	Remediate as advised for each Application	See Application			
Engagement Development Platform	3.0	Yes. CE 3.0 and AMS 7.6 are impacted.	04/30/15	PCN1983S	http://support.avaya.com/css/P8/documents/101002910	
Avaya Agile Communication Environment	3.0.x	No longer bugfix supported - upgrade to newer release	NA		https://downloads.avaya.com/css/P8/documents/101012063	https://ecm.avaya.com/wccf/wccproxy/d?id=2126350&rendition=web
	6.2.x	Yes	06/16/15	PSN004524		
Avaya Aura® Messaging	6.1	EoMS - upgrade to newer release	NA	AAM Support Page		
	6.2	EoMS - upgrade to newer release	NA			
	6.3	EoMS - upgrade to newer release	NA			
	6.3.1	EoMS - upgrade to newer release	NA			
	6.3.2	Security Patch SSP6	03/31/15			
	6.3.3	Security Patch SSP6	TBD			
IP Office Platform	7.0	No	NA			
	8.0	No	NA			
IP Office Platform including: IP Office Server Edition	8.1.x	No	NA			
	9.x	No	NA			
IP Office Application Server	8.x	No	NA			
	9.x	No	NA			
IP Office Contact Center	9.0	No	NA			
Avaya Aura® Call Center Elite	5.2.1	EoMS - upgrade to newer release	NA	PSN020178u		
	6.0.1	No longer bugfix supported - NTP provided by System Platform so no RHEL kernel vulnerability - upgrade to newer release	NA			

<http://support.avaya.com/css/P8/doc>

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
	6.2	No longer bugfix supported - NTP provided by System Platform so no RHEL kernel vulnerability - upgrade to newer release	NA		https://support.avaya.com/css/P8/documents/101008265	
	6.3	NTP provided by System Platform so no RHEL kernel vulnerability	NA			
Avaya Aura® Contact Center	6.1	No	NA			
	6.2	No	NA			
	6.3	No	NA			
	6.4.x	No	NA			
Avaya Contact Center Select	6.4	No	NA			
Avaya Aura® Experience Portal - Avaya Linux Offer	6.0.x	No known adverse effect to product operation. We will place updated tzdata RPMs on support.avaya.com for customers that choose to install them. Instructions for updating the tzdata RPMs and Oracle JRE TZUPDATER are already in place.	03/30/15	PSN003432u	https://downloads.avaya.com/css/P8/documents/100149873	
	7.0.x	No known adverse effect to product operation. We will place updated tzdata RPMs on support.avaya.com for customers that choose to install them. Instructions for updating the tzdata RPMs and Oracle JRE TZUPDATER are already in place.	03/30/15			
Avaya Aura® Experience Portal - SW Only Offer	all releases	No known adverse effect to product operation. Customers that desire this fix should obtain the most recent tzdata RPMs from Red Hat. Instructions for updating the tzdata RPMs and Oracle JRE TZUPDATER are already in place.	03/30/15	PSN003432u	https://downloads.avaya.com/css/P8/documents/100149873	
Avaya Voice Portal - Avaya Linux Offer	5.1.x	This release is no longer supported.	NA			
Avaya Voice Portal - SW Only Offer	5.1.x	This release is no longer supported.	NA			
Avaya Aura® Workforce Optimization	11.0	No required Product change. Follow Linux OS recommendations	NA			
	12.0	No required Product change. Follow Linux OS recommendations	NA			
Avaya Call Recorder (SW Only)	Linux releases	Inactive/Not Supported	NA			
Avaya Call Management System (CMS)	14.x	Inactive/Not Supported - Per Oracle there is no impact.	NA			
	15.x	Inactive/Not Supported	NA	PSN004214u	https://downloads.avaya.com/css/P8/documents/101008946	
	16.x	No	NA			
	17.0.x	Yes, one time patch	04/01/15			
Avaya Contact Center Express		No	NA			
Intelligent Customer Routing	6.0	No known adverse effect to product operation. Instructions for updating the tzdata RPMs and Oracle JRE TZUPDATER are already in place in a PSN. The PSN will be updated to include note for leap second support.	04/07/15	PSN004337u	https://downloads.avaya.com/css/P8/documents/101001806	
	7.0	No known adverse effect to product operation. Instructions for updating the tzdata RPMs and Oracle JRE TZUPDATER are already in place in a PSN. The PSN will be updated to include note for leap second support.	04/07/15			
Interaction Center	7.2					
	7.3					
IP Agent	7.0					
IQ	5.1	Not Supported	NA			
	5.2.x	No known adverse effect to product, however one time patch will be released to update the required RPMs	TBD			
IQ SW Offer	all releases					
Proactive Contact	4.2.x	No known adverse effect to product operation. PSN to be released with steps to updated tzdata rpm for customers who are not using NTP.	NA	PSN		
	5.1.x	No known adverse effect to product operation. PSN to be released with steps to updated tzdata rpm for customers who are not using NTP.	NA	PSN		
Proactive Outreach Manager	2.0	No known adverse effect to product operation. Updates will be covered as part of platform (AAEP)	NA			
	2.5	No known adverse effect to product operation. Updates will be covered as part of platform (AAEP)	NA			
	3.0.x	No known adverse effect to product operation. Updates will be covered as part of platform (AAEP)	NA			
Avaya Aura® Virtualized Environment	1.0	Remediate as advised for each Application	See Application			
Avaya Session Border Controller for Enterprise	4.0	No longer supported - upgrade to newer release	NA			
	6.2.1 Q18	No impact	NA	PSN004516u	https://downloads.avaya.com/css/P8/documents/101011789	https://ecm.avaya.com/wccf/wccproxy/4?did=2125953&R
	6.3.x	No impact	NA	PSN004516u		
Communication Server 1000	6.0	No longer supported - upgrade to newer release	NA			
	7.0	No longer supported - upgrade to newer release	NA			
	7.5	No longer supported - upgrade to newer release	NA			
	7.6	Patch will be provided for R7.6 and fix will also be included in SP7.	05/06/15	PSN004494u	https://downloads.avaya.com/css/P8/documents/101010624	
Avaya Aura® Performance Center	7.1	No known adverse effect to product operation. We will support tzdata rpm for RedHat patch.	NA			
Contact Flow Analytics	7.0					
Control Manager	7.0	No	NA			
	7.1	No	NA			

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
	Service Provider Edition 7.0	No	NA			
ANAV	4.1	No	NA			
Avaya Aura® Conferencing Standard Edition	6.x	See Aura Meeting Exchange 5.2	NA	PSN004446u	http://support.avaya.com/css/P8/documents/101008525	
Avaya Aura® Conferencing	6.0.x	No	NA			
	7.0	Yes, customers will need to move to 7.2 SP7	NA	PSN	TBD	TBD
	7.2.x	Yes, one-time patch via service pack 7.2 SP7	TBD	PSN	TBD	TBD
	8.0	Yes, one-time patch via feature pack 8.0 FP3	TBD	PSN	n/a	n/a
Avaya Aura® Orchestration Designer	6.0	Not impacted. No remediation needed. User is responsible for desktop maintenance.	NA			
	7.0	Not impacted. No remediation needed. User is responsible for desktop maintenance.	NA			
Avaya one-X® Agent	2.5.8 H.323	No	NA			
	2.5	No	NA			
	2.5.3 (SP)	No	NA			
	2.5.4 H.323	No	NA			
	2.5.6 (FP)	No	NA			
	4.2	No				
Avaya NES Contact Center Express	4.2	No				
Basic Call Management System Reporting Desktop	2.4					
Context Store Snap-in	3.0	No	NA	NA	NA	NA
Media Processing Server MPS 500 & MPS 1000	3.x (oracle based)	Instructions for using Oracle JRE TZUPDATER will be released in a PSN.	03/31/15	PSN004484u	http://downloads.avaya.com/css/P8/documents/101009973	
	4.x (oracle based)					
	3.x (Windows based)	Instructions for using Oracle JRE TZUPDATER will be released in a PSN.	03/31/15			
	4.x (Windows based)					
Media Processing Server MPS 1000	4.x (RHEL based)	Instructions for updating the tzdata RPMs will be released in a PSN.	03/31/15			
	3.x (RHEL based)		4/21/2015	PSN004484u		
Operational Analyst	4.x (RHEL based)		4/21/2015			
	7.1	AIC and OA products are not impacted by this change as they rely on OS and Java timezone. The customers would need to apply the respective OS patch and run Java TZUpdater tool.	EoMS	PSN004472u	http://downloads.avaya.com/css/P8/documents/101009257	
	7.2	AIC and OA products are not impacted by this change as they rely on OS and Java timezone. The customers would need to apply the respective OS patch and run Java TZUpdater tool.	04/09/15			
	7.3	AIC and OA products are not impacted by this change as they rely on OS and Java timezone. The customers would need to apply the respective OS patch and run Java TZUpdater tool.	04/09/15			
Outbound Contact Express	1.0	Application Specific	NA			
Real-Time Speech Snap-in	3.0	No	NA			
Speech Analytics	2.0	Inactive/Not Supported	NA			
Speech Search Engine	6.0	No	NA			
Desktop Speech Search Platform	2.0	Inactive/Not Supported				
Work Assignment Snap-in	3.0	No	NA			
1100 Series IP Deskphones	SIP 4.4	No	NA	No PSN planned for the devices themselves.		
	UNiStim 5.5	No - Time is controlled by CS1K, AS5300, CS2100.	NA			
1200 Series IP Deskphones	1.0 (UNiStim)	No - Time is controlled by CS1K, AS5300, CS2100.	NA			
	SIP 4.4	No	NA			
1400 Series Digital Deskphones	1.0	No - dependent on CM or SM for remediation	NA			
1600 Series IP Deskphones	H.323 1.3	No - time is controlled by CM (H.323) and/or IP Office	NA			
1692 IP Conference Phone	1.4	No - dependent on CM or SM for remediation	NA			
2000 Series IP Deskphones	5.0	No - time is controlled by CS1K.	NA	No PSN planned for the devices themselves. Should be included in CS1000 PSN, if required		
2033 IP Conference Phone	2.0	No - dependent on CM or SM for remediation	NA			
2050 IP Softphone	4.4	No - time is controlled by CS1K.	NA	No PSN planned for the devices themselves. Should be included in CS1000 PSN, if required		
2400 Series Digital Telephones	1.0	No - dependent on CM or SM for remediation	NA			
3600 Series IP Wireless Handsets	3.0	Inactive/Not Supported	NA			
9400 Series Digital Deskphones	1.0.x	No - dependent on CM or SM for remediation	NA			
9500 Series Digital Deskphones	1.0	No - dependent on CM or SM for remediation	NA			
9600 Series IP Deskphones	H.323 3.2	No - dependent on CM or SM for remediation	NA			
9601/9608/9608G/9611G/9621G/9641G	SIP 2.6	No - dependent on CM or SM for remediation	NA			
	H.323 6.3.x	No - dependent on CM or SM for remediation	NA			
	H.323 6.4	No - dependent on CM or SM for remediation	NA			
	SIP 6.3.x	No - dependent on CM or SM for remediation	NA			
	SIP 6.4	No - dependent on CM or SM for remediation	NA			
G860 Media Gateway	Solaris EMS					
	Linux EMS					
AudioCodes Mediant 3000 Gateway	Solaris EMS					
	Linux EMS					
Avaya Aura® Application Server 5300	2.x	Inactive/Not Supported	NA			
	3.x	Yes, bundled patch	03/06/15	PSN004440u	https://downloads.avaya.com/css/P8/documents/101008214	
Avaya Integrated Management	6.0					
Avaya Virtual Application Manager	6.2.x	No - No risk if using NTP.	NA			
B100 Series Conference Phones	B169	No	NA			
	B169 Conference	No - No impact but can adjust manually if desired	NA			

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
	B189 H.323	No - dependant on CM or SM for remediation	NA			
	B179 SIP 2.4	No - dependant on CM or SM for remediation	NA			
B5800 Branch Gateway	6.1	No	NA			
	6.2	No	NA			
Business Communication Manager BCM-50, BCM-450	6.x	No	NA			
Avaya Engagement Designer Collaboration Designer Snap-in	3.0	No	NA			
Common Servers	2.0	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
Desktop Video Device	1.2.1	No	NA			
E129 SIP Deskphone	1.0	No - dependant on CM or SM for remediation	NA			
E159 Media Station	1.1	No - dependant on CM or SM for remediation	NA			
E169 Media Station	1.0	No - dependant on CM or SM for remediation	NA			
Easy Management	6.0	No	NA			
IP DECT Phones	4.4	No - Dependant on CM or SM for remediation. There should not be any problem for Ascom systems.	NA			
S8300 Server	NA	No	NA			
S8400 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
S8500 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
S8510 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
S8720 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
S8730 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
S8800 Server	NA	NTP helps adjust for leap-second but need for remediation is dependent on application running on the Server. Please see appropriate application for remediation information.				
Software Communication System	4.0	NA	NA			
Summit Series Endpoints	NA	No - Dependant on CM or SM for remediation	NA			
Visualization Performance and Fault Manager	2.x	No	NA			
	3.x	No	NA			
WLAN Handset 6100 Series	3.0	No - Dependant on CM or SM for remediation	NA			
Automated Chat	2.0	No	NA			
AvayaLive® Collaboratory	1.0	No	NA			
Avaya Messaging Service	1.0	No	NA			
AvayaLive Video	NA	No	NA			
Cloud Enablement for Customer Experience Management	NA	See PSN				

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
Cloud Enablement for Unified Communications	1.0	See PSN	https://downloads.avaya.com/css/P8/documents/101011790			
	1.1	See PSN				
	1.2	See PSN				
Cloud Enablement for Unified Communications POD	1.2	See PSN				
Cloud Enablement for Video	1.0	See PSN				
Social Media Analytics	5.0					
Avaya CallPilot®	5.0	No	NA			
	5.1	No	NA			
Avaya Client Applications	6.3.x	No	NA			
	6.4	No	NA			
Avaya Communicator for Android	2.0.x	No	NA			
Avaya Communicator for iOS	NA					
Avaya Communicator for iPad	2.0	No	NA			
Avaya Communicator for iPhone	NA	No	NA			
Avaya Communicator for Microsoft Lync	6.4	No	NA			
Avaya Communicator for Windows	2.0.x	No	NA			
Avaya Flare® Communicator iPad	1.0	No	NA			
Avaya Flare® Communicator Windows	1.0	No	NA			
Avaya Flare® Experience	1.0	No	NA			
Avaya Flare® Experience iPad	1.1	No	NA			
	1.2	No	NA			
Avaya Flare® Experience Windows	1.1	No	NA			
Avaya Aura® Media Server	6.4	No	NA			
	7.0	No	NA			
	7.5	No	NA			
	7.6	No	NA			
	7.7	No	NA			
Avaya one-X® Attendant	3.0	No	NA			
	4.0.x	No	NA			
Avaya one-X® Client Enablement Services	6.1.x	Yes - update to 6.2.3 SP1	3/30/15	No PSN, just release notes		None
	6.2.2	Yes - update to 6.2.3 SP1	3/30/15	No PSN, just release notes		
	6.2.3	Yes - update to 6.2.3 SP1	3/30/15	http://support.avaya.com/css/P8/documents/101011974		
Avaya one-X® Communicator	6.0	No	NA			
	6.1.x	No	NA			
	6.2.6 (FP)	No	NA			
Avaya one-X® Communicator for Mac OS X	1.0.x	No	NA			
	2.0.x		NA			
Avaya one-X® Mobile	1.1	No	NA			
	5.2	No	NA			
	6.1	No	NA			
Avaya one-X® Mobile SIP for iOS	1.0.x	No	NA			
	6.2.x	No	NA			
Avaya one-X® Portal	1.1					
	5.2					
Avaya one-X® Speech	4.0	No	NA			
	5.2	No	NA			
	6.3	No	NA			
Hospitality Messaging Server 400	3.0	No	NA			
Avaya Meeting Exchange	5.2.x	Yes	03/17/15	PSN004446u	http://support.avaya.com/css/P8/documents/101008525	
	6.2.x	No				
Avaya Message Networking	3.1	Yes - migrate to 6.3 Patch 3		Release notes, no PSN		
	5.2.x	Yes - migrate to 6.3 Patch 3				
	6.3.x	Yes - apply 6.3 Patch 3				
Avaya Multimedia Messaging	2.1	Yes	TBD	PSN		
VDI Communicator	1.0	No	NA			
Modular Messaging (Avaya Message Storage Server)	3.1	No - No longer supported - upgrade to newer release	NA			
	5.2	Release notes, no PSN	06/26/15	https://support.avaya.com/downloads/download-details.action?contentid=C2015626155231900_0&productid=P0042&releaseid=523	https://support.avaya.com/css/P8/documents/101011945	
Scopia® Desktop Client	all releases					
Scopia® Mobile	all releases					
Scopia® Desktop Server	all releases					
Scopia® Elite 5000		No	NA			
Scopia® Elite 6000		No	NA			
Scopia® SIP gateway - Hardware - Only used with IBM Sametime deployments		No	NA			
Scopia® UC gateway - Hardware		No	NA			
Scopia® ISDN gateway - Hardware	all releases	No	NA			
Scopia® Management	Linux version	Synchronize time with NTP				
Scopia® Pathfinder	NA	Synchronize time with NTP				
Scopia® XT	all releases	No	NA			
Scopia® 100 MCU - Hardware - EOS - 11/16/2015	all releases	No	NA			
Scopia® 400 MCU - Hardware - EOS - 5/15/2015	all releases	No	NA			
Scopia® 3G Gateway - Hardware - EOS 11/30/2014	all releases	No	NA			
Scopia® Serial Gateway (S40) - Hardware	all releases	No	NA			
CVLAN						
Avaya Scopia Streaming & Recording	part of Scopia 8.3 FP2		TBD			
Web Collaboration Service	1.0; part of Scopia 8/3 FP2		TBD			
Avaya Branded IPO/POCC	1.0 (in Google)	NA	See Application			
Operations Support System 1.0 (OSS)	1.0 (OSS)	No	TBD			
Control Manager	7.0	No	NA			
	7.1	No	NA			
	Service Provider Edition 7.0	No	NA			
Automated Chat	2.0	No	NA			
Cloud Enablement for Customer Experience Management	NA	NA	See Application			

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
Networking Products						
Configuration and Orchestration Manager (COM)	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Configuration and Orchestration Manager (COM-VPS)	COM 3.1 VPS 1.1	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Virtualization Provisioning Service (VPS)	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
IP Flow Manager (IPFM)	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Visualization Fault and Performance Manager (VPFM)	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Pod Orchestration Suite	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
VPN Gateway	3050	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
	3070	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
	3090	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Identity Engines Ignition Server	9.0	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Collaboration Pod on VMware vCenter Server Appliance 5.x	C-Pod 2.0	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Collaboration Pod Secure Remote Access (SRA)	1.0.1.1 on C-P	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Wireless LAN 8100	all releases	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Wireless LAN 9100 WOS	with AOS 7.0.	No. If the NTP server adjusts for time (daylight savings time, leap year, leap second, etc) the networking products will adjust as well.	NA			
Services Support Tools						
Secure Access Link (SAL) GW	1.x, 2.x	No. Don't foresee any issue.	NA			
Avaya Diagnostic Server (ADS)	1.x, 2.x	No. Don't foresee any issue.	NA			
Secure Access Remote Access Concentrator	5.x, 6.x	No. Don't foresee any issue.	NA			
Secure Access Core Concentrator	5.x, 6.x	No. Don't foresee any issue.	NA			
Secure Access Link GAS	5.x, 6.x	No. Don't foresee any issue.	NA			
Secure Access Link Policy Server	1.5	No. Don't foresee any issue.	NA			
Services VM	1.x	No. Don't foresee any issue.	NA			
Services VM	2.x, 3.x	No. Don't foresee any issue.	NA			
SAL GW virtual app	1.x	No. Don't foresee any issue.	NA			
ADS virtual app	2.x	No. Don't foresee any issue.	NA			
EXPERT®	All	No. Don't foresee any issue.	NA			
Diagnostics and Tools	All	No. Don't foresee any issue.	NA			
SSG	5	No. Don't foresee any issue.	NA			
SAL GW 1.8 on System Platform	6.0 & 6.0.3.x	No. Don't foresee any issue.	NA			
ION API Technologies Corp SA5600-SAL	All	No. Don't foresee any issue.	NA			
ION ASG Defender	All	No. Don't foresee any issue.	NA			
AIM Common Server		No. Don't foresee any issue.	NA			
EPT						
Dynamic Routing		No. All products are using NTP and didn't foresee any issue.	NA			
Dynamic Self Service		No. All products are using NTP and didn't foresee any issue.	NA			
Callback Assist	4.1	No. All products are using NTP and didn't foresee any issue.	NA			
Social Media Manager	6.2	No. All products are using NTP and didn't foresee any issue.	NA			
Call Flow Analytics 7.0 module		No. All products are using NTP and didn't foresee any issue.	NA			
Avaya Speech Analytics module		No. All products are using NTP and didn't foresee any issue.	NA			
Context Store 1.x		No. All products are using NTP and didn't foresee any issue.	NA			
Avaya Voice Portal / Avaya Proactive Contact Connector		No. All products are using NTP and didn't foresee any issue.	NA			
RTDS		No. All products are using NTP and didn't foresee any issue.	NA			
One Touch Video		No. All products are using NTP and didn't foresee any issue.	NA			
ACC Controls		No. All products are using NTP and didn't foresee any issue.	NA			
VDI-Agent (and variants)		No. All products are using NTP and didn't foresee any issue.	NA			

Leap Second Impact Update for Avaya Products

Application / Product Name	Release	Remediation Needed (Y/N) and Type (e.g. one-time patch, bundled patch, manual updates, etc.).	Fix Available	Where documented? (Release Notes, PSN, etc.)	Links (Note: May be 24 hr delay in when info is available and when visible on support)	Supplemental Links
Avaya CMS / Avaya IQ Connectors		No. All products are using NTP and didn't foresee any issue.	NA			
CRM connector		No. All products are using NTP and didn't foresee any issue.	NA			
SAP		No. All products are using NTP and didn't foresee any issue.	NA			
SFDC		No. All products are using NTP and didn't foresee any issue.	NA			
WebSoftphones		No. All products are using NTP and didn't foresee any issue.	NA			
Desktop Wallboard		No. All products are using NTP and didn't foresee any issue.	NA			
Contact Analyzer		No. All products are using NTP and didn't foresee any issue.	NA			
Ajax Toolbar API		No. All products are using NTP and didn't foresee any issue.	NA			
Mobile Activity Assistant		No. All products are using NTP and didn't foresee any issue.	NA			
Avaya Notification Service		No. All products are using NTP and didn't foresee any issue.	NA			