Product Support Notice

© 2015 Avaya Inc. All Rights Reserved.

PSN #	PSN004516u

Original publication date: 19-Jun-15. This is Issue #02, published date: 29-Jun-15.

Severity/risk level: Medium

Urgency: Immediately

Name of problem

ASBCE Leap Second Update June 2015

Products affected

ASBCE 6.2.1 Q18, 6.3, 6.3 SP1, and 6.3 SP2

Problem description

On June 30th 2015, a leap second will be added to keep UTC clocks in sync with global rotation. This second will be added at 06-30-2015 23:59:60.Avaya SBCE Implementation guidelines recommend using network NTP servers. If for some reason NTP is not being used for clock synchronization, or if the enterprise NTP server that ASBCE gets its clock sync from does not support accounting for leap seconds, then the leap second will not be properly accounted for by ASBCE.

Resolution

No impact for ASBCE servers running 6.2.1 Q18, 6.3, 6.3 SP1, and 6.3 SP2 releases

Workaround or alternative remediation

NTP will allow the time adjustment to occur automatically. If there is no NTP configured, the time adjustment will have to be done manually

Remarks

n/a

Patch Notes

The information in this section concerns the patch, if any, recommended in the Resolution above.

Backup before applying the patch

n/a

Download

n/a

Patch install instructions — **Service-interrupting?**

n/a — No

Verification

n/a

Failure

n/a

Patch uninstall instructions

n/a

Security Notes

The information in this section concerns the security risk, if any, represented by the topic of this PSN.

Security risks

n/a

Avaya Security Vulnerability Classification

Not Susceptible

Mitigation

n/a

If you require further information or assistance please contact your Authorized Service Provider, or visit support.avaya.com. There you can access more product information, chat with an Agent, or open an online Service Request. Support is provided per your warranty or service contract terms unless otherwise specified in the Avaya support Terms of Use.

Disclaimer: ALL INFORMATION IS BELIEVED TO BE CORRECT AT THE TIME OF PUBLICATION AND IS PROVIDED "AS IS". AVAYA INC., ON BEHALF OF ITSELF AND ITS SUBSIDIARIES AND AFFILIATES (HEREINAFTER COLLECTIVELY REFERRED TO AS "AVAYA"), DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND FURTHERMORE, AVAYA MAKES NO REPRESENTATIONS OR WARRANTIES THAT THE STEPS RECOMMENDED WILL ELIMINATE SECURITY OR VIRUS THREATS TO CUSTOMERS' SYSTEMS. IN NO EVENT SHALL AVAYA BE LIABLE FOR ANY DAMAGES WHATSOEVER ARISING OUT OF OR IN CONNECTION WITH THE INFORMATION OR RECOMMENDED ACTIONS PROVIDED HEREIN, INCLUDING DIRECT, INDIRECT, CONSEQUENTIAL DAMAGES, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF AVAYA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

THE INFORMATION PROVIDED HERE DOES NOT AFFECT THE SUPPORT AGREEMENTS IN PLACE FOR AVAYA PRODUCTS. SUPPORT FOR AVAYA PRODUCTS CONTINUES TO BE EXECUTED AS PER EXISTING AGREEMENTS WITH AVAYA.

All trademarks identified by ® or ™ are registered trademarks or trademarks, respectively, of Avaya Inc.
All other trademarks are the property of their respective owners.

BusinessPartner Notes

Additional information for BusinessPartners

n/a

Avaya Notes

Additional information for Tier 3, Tier 4, and development

n/a

© 2015 Avaya Inc. All Rights Reserved.