



End of Sale Notice

Notification Date: 29-JUNE-2015

Revision Date: 29-JUNE-2015

Effective Date: 31-Aug-2015

Subject: End of Sale –

Avaya S8730 Server and S8800 Server Spare Parts

Theatre/Region: Global

Revision History

Revision Date	Reason for change
1-June-2015	Original

Summary

Effective **31-August-2015** Avaya will no longer sell (make commercially available) the following Spare Parts for the S8730 and S8800 servers as supported within the Avaya Common Servers portfolio.

Material Code	Description
266020	S8730 MSS-H MG KIT LG SYS
266021	S8730 MSS-H MG MED SYS
266022	S8730 MAS-H MG KIT
700405541	AM H100 BUS CBL 3 CONNECTOR RHS
700437197	S8730 MEDIA SERVER HP DL385
700445794	S8730 RAID DRIVE
700446578	APC HP DL385 DISK DRIVE 146GB
700446586	APC HP 4GB PC2-5300 2x2GB MEM
700454135	2GB Memory Module for 1950V3 SRVR (2x1GB)
700453871	PE1950 Power Supply
700461114	S8730 SRVR HP DL385G5 w/DUALCORECPU
700465685	MM HP DL385 72GB 15K SAS DSK DRIVE
262600	S8800 MSS MIGRATION KIT
700476930	S8800 MX 2U SRVR RCDG SRVR
700478274	S8800 SRVR 2GB MEMORY
700478308	S8800 SRVR POWER SUPPLY 675 WATTS



700478621	S8800 1U SRVR MM MSS
700478902	S8800 MM MAS MISC COMPONENTS KIT
700479835	APC S8800 SRVR 146GB 10K SAS DRIVE
700479892	S8800 MM MSS MISC COMPONENTS KIT
700500443	MIDSIZE APP 1950V3 PERC6I RAID BATTERY
700503278	S8800 NIC FIELD REWORK KIT

To allow any remaining valid quotes to be converted to orders, the order codes for the above spare parts will remain in a sales status of “Available/G*” until the End of Sale (EoS) effective date, after which, the codes will be changed into a sales status of “MD/D*” or “M*”. Please note that Avaya will respond to orders subject to availability of inventory.

Discontinued Order Codes and Migration Strategy

Limited Availability Codes

The following material codes will be changed to a sales status of “L/MRSD” in preparation of going EoS on the 14-Dec-2015.

Material Code	Description
262600	S8800 MSS MIGRATION KIT
700479892	S8800 MM MSS MISC COMPONENTS KIT

The following material codes will be changed to a sales status of “L/MRSD” in preparation of going into the “M” sales status on the 14-Dec-2015.

Material Code	Description
700479835	APC S8800 SRVR 146GB 10K SAS DRIVE

Discontinued Codes

The following material codes will be changed to a sales status of “MD/D*”

Material Code	Description
266020	S8730 MSS-H MG KIT LG SYS
266021	S8730 MSS-H MG MED SYS
266022	S8730 MAS-H MG KIT
700437197	S8730 MEDIA SERVER HP DL385
700445794	S8730 RAID DRIVE



700461114	S8730 SRVR HP DL385G5 w/DUALCORECPU
700476930	S8800 MX 2U SRVR RCDG SRVR
700478621	S8800 1U SRVR MM MSS
700478902	S8800 MM MAS MISC COMPONENTS KIT

Maintenance Codes

The following material codes will be changed to a sales status of "M**"

Material Code	Description
700405541	AM H100 BUS CBL 3 CONNECTOR RHS
700446578	APC HP DL385 DISK DRIVE 146GB
700446586	APC HP 4GB PC2-5300 2x2GB MEM
700454135	2GB Memory Module for 1950V3 SRVR (2x1GB)
700453871	PE1950 Power Supply
700465685	MM HP DL385 72GB 15K SAS DSK DRIVE
700478274	S8800 SRVR 2GB MEMORY
700478308	S8800 SRVR POWER SUPPLY 675 WATTS
700500443	MIDSIZE APP 1950V3 PERC6I RAID BATTERY
700503278	S8800 NIC FIELD REWORK KIT

System Expansion post-End of Sale

There will be no provision for system expansions post the end of sale.

Migration Strategy

With the end of sale for the S8730 and S8800 server spare parts there will be no migration strategy implemented and hence there are no alternate material codes available.

Schedule

End of Sale Date (last day to order new systems)	31-August-2015
End of Manufacturer Support for SOFTWARE **	n/a
End of Manufacturer Support for HARDWARE	31-August-2016
Last day to purchase system expansions	n/a
Last day to purchase a new Avaya services contract **	31-August-2016
Targeted End of Services Support	31-August-2021***

** Per Avaya Product Lifecycle Policy

*** Avaya Services may revise the Target End of Services Support date based on the availability of quality repair parts and/or technical support expertise. Customers should always consult any available product Services Support Notices for final information on product supportability.



Service and Warranty

Avaya will continue to honor previously executed enhanced warranty, post-warranty and service contracts in accordance with the terms of those agreements. Avaya is not responsible for any support or maintenance commitments made by Business Partners or other service providers. Additional information concerning Avaya Services can be found on the [Services Offer Information](#) Web site.

Renewals of existing Avaya service contracts covering this product will be allowed until further notice.

Supply Availability

Avaya will make every effort to supply the S8730 and S8800 server spare part components for all orders, but cannot guarantee product availability through the End of Sale date. Avaya reserves the right to manage and/or limit order quantities, or to cancel orders if supply is no longer available. Customer orders will be fulfilled on a first-come, first-served basis. If supply is exhausted prior to the targeted End of Sale date in this notice Avaya will accelerate removal of the applicable product codes from price lists and associated order entry systems. If supply is no longer available requiring order cancellation then customers will be notified.

Glossary

G*	Generally Available
D*	Discontinued
MD	Manufacture Discontinued
M*	Maintenance
L*	Limited Availability
MRSD	Manufacture Retired Stock Depletion

Additional Information

Avaya website:

<http://www.avaya.com>

Avaya End-of-Sale Notices:

<http://support.avaya.com>

Avaya Product Lifecycle Policy:

<https://support.avaya.com/css/P8/documents/100081098>

or

<http://support.avaya.com> >> More Resources >> More >> Avaya Product Lifecycle Policy