

Special Placement Guidelines for TN2302AP HV11 in the CMC1 Media Gateway

CAUTION:

The **TN2302AP** media processor circuit pack, hardware vintage **HV11**, should not be placed in slots 5 or 10 of a CMC1 media gateway. Placing it in these slots may cause excessive radio emissions at 200 MHz.

Vintages of the TN2302AP other than HV11 may be used in any CMC1 port slot. Media gateways other than the CMC1 do not have any special placement restrictions.

