



Retirement Bulletin

Bulletin Number: R-2007-0052-Global Date: 01 March 2007

Ethernet Switch 450 (formerly BayStack 450) Manufacturing Discontinue effective 1st March 2007

REVISION HISTORY

| Date | Revision # | Summary of Changes |
|-------------------|------------|----------------------------------|
| February 21, 2007 | 1.0 | This is the original publication |
| | | |
| | | |

Customer Notification of the decision to manufacture discontinue the Product noted above:

| Last Time Order Date: | 31 May 2007 |
|------------------------------------|----------------------|
| Last Ship Date: | 31 July 2007 |
| Manufacture Discontinue (MD) Date: | 01 March 2007 |
| End of Life (EOL) Date: | 31 July 2012 |
| Last Supported Software Release: | 4.5.5 |
| Market Regions Affected: | Global (except EMEA) |

<u>Introduction</u>

Effective 1st March 2007, the Nortel Ethernet Switch 450 series (formerly BayStack 450) is hereby declared manufacturing discontinued. The last time order date is 31st May 2007, with the last ship date of 31st July 2007. Customers are encouraged to purchase Ethernet Routing Switch 4500 Series switches or the Ethernet Switch 470/470-PWR when a 24-port switching option is required, which offer vastly improved functionality to the ES 450 series switches.

Definition

Nortel Page 1 of 4

Manufacture Discontinue (MD) – This notice serves as formal communication of Nortel Networks' intent to MD the product(s) noted. No further orders will be accepted as of the Last Time Order Date shown above and no further shipments made after the product has been discontinued. The MD of these products should not be interpreted as the discontinuance of any Nortel Networks agreements to support the existing field population. Services to the existing product base will continue to be provided until the End of Life (EOL) date shown above.

Product Overview (See Table for Detail)

| Product Description | Product Engineering | |
|--------------------------|---------------------|--|
| | Code (PEC) | |
| Ethernet Switch 450-24T | AL2012?14* | |
| Ethernet Switch 450-12T | AL2012?15* | |
| Ethernet Switch 450-12F | AL2012?19* | |
| 450-2FX MDA | AL2033002 | |
| 450-4FX MDA | AL2033003 | |
| 450-4TX MDA | AL2033004 | |
| 450-1SX MDA | AL2033005 | |
| 450-1SR Linksafe MDA | AL2033006 | |
| 450-1LX MDA | AL2033007 | |
| 450-1LR Linksafe MDA | AL2033008 | |
| 450-1GBIC GBIC MDA | AL2033009 | |
| Ethernet Switch 450-12T, | AL2011006 | |
| 450-24T Rack Mount | | |
| Replacement Kit | | |

Note: * The seventh character (?) of the switch order number must be replaced with the proper code to indicate desired product nationalization.

Software Dependencies

Ethernet Switch Software v4.5.5 (29 March 2006) will be the last major software version supported on the Ethernet Switch 450 series products.

Nortel Page 2 of 4

Alternative/Replacement Products

| Product Description | Product Engineering Code (PEC) | Replacement Product Description (Recommendation in order) | Replacement Product Engineering Code (PEC) |
|-------------------------|--------------------------------------|---|--|
| ES450-24T | AL2012?14* | Ethernet Routing Switch 4550T Ethernet Routing Switch 4550T-PWR Ethernet Switch 470-24T Ethernet Switch 470-24T-PWR | AL4500?02-E6* AL4500?12-E6* AL2012?37-E5* AL2012?53-E5* |
| ES450-12T | AL2012?15* | Ethernet Routing Switch 4550T Ethernet Routing Switch 4550T-PWR Ethernet Switch 470-24T Ethernet Switch 470-24T-PWR | AL4500?02-E6* AL4500?12-E6* AL2012?37-E5* AL2012?53-E5* |
| ES450-12F | AL2012?19* | Ethernet Routing Switch 4526FX | AL4500?01-E6* |
| 450-2FX MDA | AL2033002 | 100BaseFX SFP | AA1419074-E6 |
| 450-4FX MDA | AL2033003 | 100BaseFX SFP | AA1419074-E6 |
| 450-4TX MDA | AL2033004 | N/A | N/A |
| 450-1SX MDA | AL2033005 | 1000BaseSX SFP (LC or MTRJ conn) | AA1419013-E5, or AA1419014-E5 |
| 450-1SR Linksafe MDA | AL2033006 | None | N/A |
| 450-1LX MDA | AL2033007 | 1000BaseLX SFP | AA1419015-E5 |
| 450-1LR Linksafe MDA | AL2033008 | None | N/A |
| 450-1GBIC GBIC MDA | AL2033009 | N/A | N/A |

Note: * The seventh character (?) of the switch order number must be replaced with the proper code to indicate desired product nationalization.

Related Product and Sales & Marketing Bulletins (if applicable)
None.

Customer Actions

Customers are encouraged to purchase Ethernet Routing Switch 4500 series switching products which offer increased port density and software functionality at a cheaper price than the 450 series.

Nortel Page 3 of 4

The incremental benefits are: Ethernet Routing Switch 4500 includes high-performance built-in stacking ports, two built-in SFP GBIC ports for uplinks plus support of 100BaseFX SFPs in a compact 1 RU design and are more cost-effective per port than the 450 series. There is also a 24 port 100BaseFX (MTRJ) switching model for environments where fiber to the desktop may be required. The ERS 4500 family address wiring closet requirements for both 10/100 and 10/100/1000 speeds to the desktop providing maximum flexibility in one product family.

The ERS 4500 series of products also contains a comprehensive list of software features addressing Security, Convergence and Quality of Service functions critical for today's Enterprises.

Nortel also offers another replacement option with convergence-ready Ethernet Switch 470-24T-PWR or 470-48T-PWR as these switches offer desktop connectivity and IEEE 802.3af compliant Power over Ethernet (PoE) on all ports. Other incremental benefits are: Ethernet Switch 470-PWR includes built-in stacking ports, two built-in GBIC ports for uplinks and compact 1 RU design.

*Nortel, the Nortel logo and the Globemark are trademarks of Nortel.

©2006 Nortel Networks Limited. All rights reserved. Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks Limited. All other trademarks are the property of their respective owners.

The information in this document is subject to change without notice. Nortel reserves the right to make changes, without notice, in equipment design as engineering or manufacturing methods may warrant. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel Networks Limited.

To view the most recent version of this bulletin, please visit Nortel's Partner Information Center on the web at: http://www.nortel.com/pic.

Nortel Page 4 of 4