

PSN # PSN005143u Original publication date: 2 March 2018. This is Issue #01, published Severity/risk level Medium Urgency High date: 2 March 2018. End of Transition Service Agreement (TSA) and find day to download software from Avaya Support portal on MARCH 30, 2018 for the products defined below. Software for these products WILL NOT BE AVAILABLE FROM EXTREME NETWORKS. Customer must maintain their own copies of required Products affected Frequired

ERS 5600 – all versions ERS 5500 – all versions ERS 4500 – all versions ERS 2500 – all versions WLAN 8100 Controller – all versions

ERS 4800 – all versions prior to 5.9 ERS 3500 – all versions prior to 5.3 VSP 7024 – all versions prior to 10.4

Problem description

As of March 30, Avaya will no longer provide access to software images for any Networking products which were transitioned to Extreme Networks.

Due to 3rd party software restrictions, Extreme Networks will not provide access to any software related to the products defined above.

Customers will be required to download any required images from Avaya Support prior to March 30, 2018, and to maintain copies of any required software for these products.

Resolution

Customers should download any required software images prior to March 30, 2018.

Workaround or alternative remediation

None.

Remarks

n/a

Patch Notes

The information in this section concerns the patch, if any, recommended in the Resolution above.

Backup before applying the patch	
n/a	
Download	
n/a	
Patch install instructions	Service-interrupting?
n/a	No
Verification	
n/a	
Failure	
n/a	

n/a

Security Notes

The information in this section concerns the security risk, if any, represented by the topic of this PSN. Security risks

n/a

Avaya Security Vulnerability Classification

Not Susceptible

Mitigation

n/a

If you require further information or assistance please contact your Authorized Service Provider, or visit <u>support.avaya.com</u>. There you can access more product information, chat with an Agent, or open an online Service Request. Support is provided per your warranty or service contract terms unless otherwise specified in the Avaya support <u>Terms of Use</u>.

Disclaimer: ALL INFORMATION IS BELIEVED TO BE CORRECT AT THE TIME OF PUBLICATION AND IS PROVIDED "AS IS". AVAYA INC., ON BEHALF OF ITSELF AND ITS SUBSIDIARIES AND AFFILIATES (HEREINAFTER COLLECTIVELY REFERRED TO AS "AVAYA"), DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND FURTHERMORE, AVAYA MAKES NO REPRESENTATIONS OR WARRANTIES THAT THE STEPS RECOMMENDED WILL ELIMINATE SECURITY OR VIRUS THREATS TO CUSTOMERS' SYSTEMS. IN NO EVENT SHALL AVAYA BE LIABLE FOR ANY DAMAGES WHATSOEVER ARISING OUT OF OR IN CONNECTION WITH THE INFORMATION OR RECOMMENDED ACTIONS PROVIDED HEREIN, INCLUDING DIRECT, INDIRECT, CONSEQUENTIAL DAMAGES, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF AVAYA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

THE INFORMATION PROVIDED HERE DOES NOT AFFECT THE SUPPORT AGREEMENTS IN PLACE FOR AVAYA PRODUCTS. SUPPORT FOR AVAYA PRODUCTS CONTINUES TO BE EXECUTED AS PER EXISTING AGREEMENTS WITH AVAYA.

All trademarks identified by [®] or TM are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners.